

PRIMARY CORNER DESCRIPTION Interior SW Cor. Ensley DLC #44

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated Sept. 1856

Set post interior corner, from which
 An Oak 18" dia., bears N.15°W., 168 lks.
 An Oak 15" dia., bears N.48°W., 171 lks.

F.C. Frear, Deputy Co. Surveyor - Wit: J.W. Harness; Earl
Frier - Dec. 1917 - C.S. File 1/4; Vol. 3 Page 3 and M 1-6

Renew from old BTs.
Set in an 8" x 12" x 12" sandstone, from which
 A 24" Oak bears N.15°W., 1.68 chs. dist.
 A 20" Oak bears N.50°W., 1.71 chs. dist.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 12/2/1999 - C.S. File 66/13-2

Found - 18" now 38" dia., W.Oak with a previously opened
well healed blaze, we open center rotted out, no
blazes or scribing found, bears N.15°W., 110.9
ft. OBT
 15" now 39" dia., W.Oak we open center rotted out,
no blaze or scribing found bears N.50°W., 112.9
ft.
 Corner lies at the intersection of fences running
 South & West.
Rescribe both orig. BTs on single blaze "INT DLC 44 CS BT"
Set - 2 3/8" dia., brass cap on a 1 3/8" O.D. by 32" long
iron pipe, protrudes 6" above ground.
 14" dia., D.Fir double blazed & scribed "INT DLC 44
 CS BT" bears N.44°W., 74.0 ft.
 1917 stone not found.