

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664 dated May 23, 1896 (DCSO records Vol. 4 Page(s) 1484)

Set a Fir post, 3 ft. long, 4"sq., 24" in the ground, for ¼ sec. cor. mkd. ¼ S on W. face; from which
A Cedar 18" dia., bears N.45°E., 99 lks. dist. mkd. ¼ S BT
A Fir 30" dia., bears N.50°W., 24 lks. dist. mkd. ¼ S BT.
This cor. is on a SW. slope, 150 ft. below top of ridge.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - Aug. 1961 - C.S. File 49/143-60

Found - Cedar stump, now 48", approx. 24" when scribed, N.45°E., 65.3 ft. Has been previously opened and scribing "¼S" plainly visible.
Shattered Fir stump, now 48", S.50°W., instead of N.50°W., 15.8 ft. No scar or scribing found.
No trace of stump found to the NW.
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 6 W
¼ S19 | S20
1961
New BTs -12" D.Fir S.89°E., 24.1 ft. mkd. ¼ S20 CS BT.
21" D.Fir N.55½°W., 44.5 ft. mkd. ¼ S19 CS BT.

David Edwards - Crew: Brant Miller and Eric Sprinkle - 10/23/2020 - C.S. File 65/106-49

Found - 1961 DCSO brass capped iron pipe in good condition. All of the previous BTs have rotted away.
New - A 24" dia., Fir scribed "¼ S19 BT" bears N.8°W., 16.3 ft.
A 7" dia., Fir scribed "¼ S20 BT" bears N.43°E., 23.6 ft.
Note - Compass decl. 15°E.