

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & 32 of T21-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 694)

Set ¼ sec. post, from which
A Fir 30" dia., bears N.45°W., 24 lks. dist.
A Fir 24" dia., bears S.27°E., 20 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #514, dated Aug. 27, 1884 (DCSO records Vol. 2 Page(s) 702-03)

Found gr. sec. cor. gone. Reestablished the same by setting post, 4" dia., 4 ft. long, with mkd. stone, 12" in ground, mkd. ¼ S on N. face; from which
Fir 24" dia., bears S.27°E., 20 lks. dist. mkd. ¼ S BT
Fir 30" dia., bears N.47°W., 23 lks. dist. mkd. ¼ S BT

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy; Clete Putnam, crew - Sept. 1961 - C.S. File 49/143-85

Found - Fir tree, 36", N.47°W., 15.2 ft., uprooted and down, shows good axe scar at bottom. W. Haines says he found scribing about 6 years ago. (From position this is lying impossible to chop open now.)
Badly burned Fir stump bears S.27°E., 13.2 ft. Too much gone to find scars or scribing.

Set Brass cap at cor. mkd: County Surveyors Office

T21S_{R6W} ¼ S32
T22S_{S 5}

1961

New BTs -38" Fir S.23°E., 45.5 ft. mkd. ¼ S5 CS BT, all in one blaze.

30" Fir S.42°W., 47.7 ft. mkd. ¼ S5 CS BT, all in one blaze.