

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 28 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1456)

Set 1/4 sec. post, from which
A Fir 8" dia., bears S.20°E., 34 lks. dist.
A Maple 10" dia., bears S.80°W., 24 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664 dated May 23, 1896 (DCSO records Vol. 4 Page(s) 1482)

The 1/4 sec. cor.; post decayed; at same point I reestablish this cor. as follows:
Set a sandstone 14x12x8 ins., 9" in the ground for 1/4 sec. cor. mkd. 1/4 on W. face; from which
A Fir 12" dia., bears S.20°E., 34 lks. dist. mkd. 1/4 S BT
A Cedar 10" dia., bears N.22°W., 40 lks. dist. mkd. 1/4 S BT

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - Aug. 1961 - C.S. File 49/143-57

Found - 24" Hemlock S.20°E., 22.4 ft., opened scar and find good scribing "1/4S" (Orig. notes call for Fir)
30" Cedar N.22°W., 26.4 ft., scar had been opened previously and face rotted away.
Corner stone not found, has obviously been destroyed by logging, point for corner falls in Cat Road.
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 6 W
W 1/4 | S28 only
1961
Reblazed and rescribed:
Hemlock S.20°E., 22.4 ft. "1/4 S28 CS BT".
Blaze and scribe:
40" R.Cedar N.87°W., 54.1 ft. mkd. W 1/4 S28 CS BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #1073, surveyed Aug/Sept. 1981 (DCSO records Vol. 44 Page(s) 17027-28)

At the 1/4 sec. cor. of sec. 28 only, perpetuated and recorded by Godfrey in 1961, monumented with an iron post, 1 1/4" dia., firmly set, projecting 10" above ground, with 1961 DCSO brass cap, from which the remains of an original bearing tree

(Cont. Next Page)

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 28 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A root hole bears S.20°E., 34 lks. dist. with a down Hemlock alongside, 24" dia., with scribe marks ¼ S visible on open blaze. (Rec. Fir) and a bearing tree mkd. by Nicklin
A Cedar snag 30" dia., bears N.22°W., 40 lks. dist., with axe marks visible on open blaze. and new bearing trees
A Fir 5" dia., bears N.25°E., 25½ lks. dist. mkd. X BT.
A Fir 6" dia., bears S.46°E., 16½ lks. dist. mkd. ¼ S28 BT

Ken Hoffine - For: Lone Rock Timber Co. - 5/2002 - C.S. File 65/44-15

Found - 1961 County Surveyor's cap in good condition.
26" R.Cedar snag bears N.23½°W., 26.9 ft. (rec. N.22°W, 26.4 ft) chopped out face and tag.
40" R.Cedar bears N.87°W., 54.4 ft. (Rec. N.87°W., 54.1 ft) well healed face and tag
10" D.Fir bears N.25°E, 16.4 ft (rec. N.25°E, 16.8 ft) well healed face we tag.
7" dead D.Fir bears S.46°E 10.5 ft. (rec. S.46°E, 10.9 ft) well healed race we tag.
A root hole & very rotten remains of a hemlock fd. at approximate record bearing distance (rec. S.20°E, 22.4 ft)
9" D.Fir bears S.54°E, 15.9 ft. we tag tree.
Corner lies on very gentle South slope 80 feet West of Thistleburn Creek Rock Road & 75 feet East of Thistleburn Creek.