

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 300338

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. Sec. 20 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1455) - (added to recorded 5/25/2017 JC)

-----  
Set ¼ sec. post, from which  
    A Fir 8" dia., bears S.25°E., 25 lks. dist.  
    A Dogwood 12" dia., bears S.10°W., 15 lks. dist.  
(Note: set as a common corner)

GLO survey by Nicklin, Contract #664, dated May 23, 1896 "After diligent search, I could find no trace of the ¼ sec. cor." (DCSO records, Vol. 4 Page 1483) (added to recorded 5/25/2017 JC)

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - 1961-1962 - C.S. File 49/89\* and C.S. File 49/143\*

-----  
Corner not found.  
\*Could not find any paperwork to back up this report. There is a NF C.S. 49/89 on old visual. 5/25/2017 DCSO JC

Survey by Donald Branch - For: U.S. Bank - Oct. 14, 1983 - M 95-65 - (added to recorded 5/25/2017 JC)

-----  
Per narrative:  
"The east ¼ was a protracted corner per Nicklen Survey dated 1897, the corner position was computed from the latest survey data (BLM survey in 1981 by J.E. Jelley) & measurements I made to the found monuments set in said 1981 survey."

No corner was set.  
W1/4 corner Sec. 21 bears N.1°15'E., 72.15' per map.