

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1449)

Set post cor. of secs. 4, 5, 8 and 9, from which
A Maple 8" dia., bears N.40°E., 5 lks. dist.
A Maple 6" dia., bears N.28°W., 5 lks. dist.
A Maple 8" dia., bears S.38°W., 3 lks. dist.
A Fir 6" dia., bears S.23°E., 51 lks. dist.

Survey by George Scroggin - For Plat of Sunnydale Orchards - Aug. 6, 1914 - Plat Vol. 5 Page 20 S&B

Iron Rod.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - Sept. 1961 - C.S. File 49/143-86

Found - 3/4" I. Rod in E. & W. fence line.
No trace of old BTs found.
Old Maple 33", bears S.23°E., 3.5 ft. Old axe scars on SE face, directly away from cor., edges of old face visible in rotten wood in hollow center of tree, but no scribing found.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 6 W
S 5 | S 4
S 8 | S 9
1961

New BTs -4" D.Fir S.5°W., 15.4 ft. mkd. S8 CS BT.
9" D.Fir N.88°E., 24.6 ft. mkd. T22S R6W S4 CS BT.
3" D.Fir S.59½°E., 23.6 ft. mkd. S9 CS BT.
4" D.Fir N.11°W., 9.5 ft. mkd. S5 CS BT.

Wilford N. Haines - June 1966 - C.S. File 51/309-4

This section corner in danger of being destroyed by road construction. Therefore, I put in reference points.

Found - DCSO brass cap and 1" Iron rod.

Set - Survey Point disk on 48" Fir, S.83½°W., 22.0 ft.
Survey Point disk on 10" Fir S.75 3/4°E., 88.82 ft.
"T" Iron, S.75 3/4°E., 41.91 ft. from corner.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 2/12/2010 - C.S. File 67/31-3

Found - 2½" dia., brass cap on a 1½" iron pipe protrudes 12" out of ground (1961)

continued next page

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

1914 ¾" iron rod along southerly edge of BC/IP protrudes 6" out of ground.
1916 SW BT gone
9" now 18" dia., 1 ft. high D.fir stump, partial blaze visible bears N.88°E., 24.6 ft. 1961
3" now 9" dia., D.Fir with a fully healed blaze bears S.59½°E., 23.6 ft. 1961
4" now down 6" dia., D.Fir with BT tag. Root hole bears N.11°W., 9.5 ft. 1961
48" dia., 4 ft. high rotted D.Fir stump, no survey disk fd. center bears S.83½°W., 24.0 ft. 1966 (Rec. S.83½°W., 22.0 ft.)
33" maple noted in 1961, we single blaze above burle 5 ft above ground scribed "X" bears S.23°E. 3.5 ft.
New - 18" dia., D.Fir double blazed & scribed "T22S R6W S4 CS BT" bears N.82°E., 26.0 ft.
11" dia., D.Fir double blazed & scribed "T22S R6W S8 CS BT" bears S.20°W., 23.6 ft.
Note - Corner lies 1 ft. South of an old E-W fence line, approx. 100 ft. east of an old logging road & cattle guard.
Compass decl. 16½°E.