

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33, T21-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 693)

Set post cor. of secs. 4, 5, 32 and 33; from which

- A Cedar 30" dia., bears S.40°E., 17 lks. dist.
- A Hemlock 20" dia., bears N.62°W., 54 lks. dist.
- A Fir 30" dia., bears S.75°W., 34 lks. dist.
- A Fir 24" dia., bears N.50°E., 47 lks. dist.

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #514, dated Aug. 27, 1884 (DCSO records Vol. 2 Page(s) 702)

Where the cor. stood, Post gone, bearing trees all gone, but one, that down. Reestablished the cor. by setting post, 6" dia., 4 ft. long, with mkd. stone, 12" in ground, mkd. T21S S33 on NE.; R6W S4 on SE.; T22S S5 on SW.; S32 on NW. face, with two notches on W. and 4 on E. edge; from which

- Fir 32" dia., bears N.52°E., 47 lks. dist., mkd. T21S R6W S33 BT.
- Fir 36" dia., bears S.50°E., 27 lks. dist., mkd. T22S R6W S4 BT.
- Fir 30" dia., bears S.17°W., 44 lks. dist., mkd. T22S R6W S5 BT.
- Fir 24" dia., bears N.52°W., 60 lks. dist., mkd. T21S R6W S32 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Clete Putnam, crew - Sept. 1961 - C.S. File 49/143-88

Found - Rock, top 4" x 8", with "X" on top and 4 notches on W. face.

- Rotted remains of Fir tree, N.52°E., 31.0 ft. No scars or scribing found. (Wright's BTs, probably)
- Rotted ring of Fir stump, S.75°W., 22.4 ft. (Orig.) Haines found fragments of reverse scribing on this stump, pieces fastened by wire to our new NW BT.
- Old remnants of Cedar stump, S.40°E., 11.2 ft., no scribing. (Orig.)

No trace found of any other old BTs.

Alongside rock, Set Brass cap at cor. mkd:

County Surveyors Office

T21S	R6W	<u>S32</u>	<u>S33</u>
T22S	S 5		S 4

(Cont. Next Page) 1961

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33, T21-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs - 8" D.Fir N.85½°W., 14.2 ft. mkd. T21S R6W S32 CSBT.
12" D.Fir N.6½°E., 23.4 ft. mkd. T21S R6W S33 CSBT.
19" D.Fir S.21½°W., 22.7 ft. mkd. T22S R6W S5 CSBT.
17" D.Fir S.20°E., 20.6 ft. mkd. T22S R6W S4 CS BT.

Cor. Fd. and Used by Akin in BLM resurvey, Group #828, surveyed Oct. 1973 (DCS0 records, Vol. 36 Page 14993)

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy - P. Earle; C. Goodwin, crew - Feb. 14, 1974 - C.S. File 56/43-15

Found - 1961 DCS0 brass cap with stone alongside.
8" now 12" D.Fir bears N.85½°W., 14.2 ft. showing healed blaze.
12" now 16" D.Fir bears N.6½°E., 23.4 ft. showing healed blaze.
SW BT is now down.
17" now 22" D.Fir bears S.20°E., 20.6 ft. showing healed blaze.
New BT - 20" D.Fir bears S.54°W., 34.9 ft. scribed T22S R6W S5 CS BT.

Fd. BC & accessories by Tony Hostetter - May 2008 - M155-71
FD. BC & 4 BTs by Kent Inman - May 2010 - M160-72A & B

Eugene Wobbe - Crew: Sean Lange & Matthew Ternyik - 7/7/2017
- C.S. File 65/95-45

Found - 2½" brass cap (properly mkd) on 1½" iron post & stone on east side of iron post.
12" D.Fir now 30" with healed face bears N.5½°E., 23.4' (Rec. N.6½°E.) - 1961 BT
17" D.Fir now 31" with healed face S.20°E., 20.4 ft. (Rec. 20.6') - 1961 BT
20" D.Fir now 33" with healed face S.54½°W., 35.0' (Rec. S.54°W., 34.9') - 1974 BT
8" D.Fir now 14" with healed face bears N.85½°W., 14.2' - 1961 BT.
New - Set alum. channel marker post with BLM land survey marker sign near corner.
Note - Bearings are based in 1973 BLM survey.