

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol 4 Page 1457)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Fir 14" dia., bears N.30°W., 18 lks. dist. A Cedar 8" dia., bears S.50°W., 76 lks. dist.</p>
<p>GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664 dated May 23, 1896 (DCSO records Vol. 4 Page(s) 1480)</p> <p>-----</p> <p>The ¼ sec. cor. post, decayed; bearing trees grown over; I reestablished this cor. at same point, as follows: Set a Chincapin post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., mkd. ¼ S on N. face, from which A Cedar 8" dia., bears S.55°W., 76 lks. dist. mkd. ¼ S BT A Fir 30" dia., bears N.48°W., 64 lks. dist. mkd. ¼ S BT.</p>
<p>Wilford N. Haines - Field Book H-106 (no date)</p> <p>-----</p> <p>Set a steel shaft 1 ft. long with a flange 4½" dia., from old BTs, A Cedar 18" dia. SW.; and A D.Fir 44" dia. NW.</p>
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - Aug. 1961 - C.S. File 49/143-55</p> <p>-----</p> <p>Found - 22" Cedar S.50°W., 50.2 ft., shows good scars. 48" Fir N.48°W., 42.2 ft., uprooted and down. Cut into scars and found good scribing "S" Set Brass cap at cor. mkd: County Surveyors Office T 22 S R 6 W ¼ $\frac{S\ 28}{S\ 33}$ 1961</p> <p>New BT - 18" I.Cedar N.26½°E., 32.0 ft. mkd. ¼ S28 CS BT.</p>
<p>Ken Hoffine - For: Lone Rock Timber Co. - 6/1/2001 - C.S. File 65/37-7</p> <p>-----</p> <p>Found - 1961 Douglas Co. brass cap. 48" stump rootwad with BLM tag & chopped out face bears N.48°W., approx. 48' (moved by tractor) 16" Cedar snag with visible scribing & BLM tag bears N.26½°E., 32.0 ft. as per record.</p> <p>New BTs- 8" D.Fir bears S.50°W., 22.7 ft. I scribe "¼ S33 BT" 7" D.Fir bears N.25°W., 4.8 ft. I scribe "¼ S28 BT"</p>
<p>continued next page</p>

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2653, Surveyed June/July 2012 - DCSO records Vol. 58 Page(s) 22986

The ¼ sec. cor. of secs 28 and 33, perpetuated by Godfrey, in 1961, from original evidence no longer in existence, further perpetuated by Hoffine, PLS No. 2291, in 2001, monumented with an iron post, 1¼" dia., firmly set, projecting 1" above ground, with brass cap (properly) mkd

from which the remains of a bearing tree mkd. by Godfrey

A decayed cedar stump, 12" dia., bears N.26½°E., 31.5 ft., alongside of which is a fallen, decayed cedar snag, 12" dia., with scribe marks ¼ S28 CS visible on an open blaze.

and bearing trees mkd. by Hoffine

A fir, 10" dia., bears S.48¾°W., 22.9 ft., with a healed blaze.

A fir, 9" dia., bears N.22°W., 5.0 ft., with a healed blaze.

Corner is located on a broken SW. slope, 30 ft. W. of a graveled road, 12 ft. wide, bears N.20°E. and S.37°W., 60 ft. W. of a graveled road, 12 ft. wide, bears S.20°E. and N.10°W., and 115 ft. E. of a graveled road, 16 ft. wide, bears S.35°E. and N.44°W.