

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664 dated May 23, 1896 (DCSO records Vol 4 Pg 1479)

-----  
Set a sandstone 12x10x6 ins., 8" in the ground, for 1/4 sec. cor. mkd. 1/4 on W. face, from which  
A Hemlock 14" dia., bears N.45°E., 16 lks. mkd. 1/4 S BT.  
A Cedar 20" dia., bears S.31°W., 11 lks. mkd. 1/4 S BT

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - Aug. 1961 - C.S. File 49/143-54

-----  
Found - Stone set by Nicklin with "1/4" on West face.  
R.Cedar now 34", N.31°W., instead of S.31°W., 7.3 ft. to center of tree. Has been previously opened, scribing "1/4S" plainly visible.  
Hemlock, down and dead, N.45°E., 10.6 ft. No scar or scribing found.  
Alongside rock, SET iron pipe with brass cap mkd: County Surveyors Office 1961 T22S R6W 1/4 S33|S34.  
Blaze and scribe:  
8" W.Fir S.39°E., 12.5 ft. mkd. 1/4 S34 CS BT.

Douglas County Surveyors Office - Larry E. Monrean, P.L. Earle, crew - April 21, 1977 - C.S. File 59/31-29

-----  
Found - Orig. stone, 3" above ground "1/4" marked on West face. Brass cap along SE edge of stone and is properly mkd.  
Orig. 20" now a 36" Cedar stump, bears N.31°W., 7.3 ft. (Orig. S.31°W.) Stump is broken off, no scribing visible.  
No other BTs found as area has been logged.  
New - Bridge spike in a 42" R.Cedar stump. Spike bears N.71°W., 41.5 ft.  
A D.Fir 10" bears S.74 1/2°E., 35.3 ft. Tree double blazed and scribed "1/4 S34 CS BT".  
This corner lies near a N-S cutting line. Corner is in clear cut to the West of line approx. 30 ft.

David Edwards - Crew: Brant Miller & Eric Sprinkle - 1/21/2011 - C.S. File 65/72-1

-----  
Found - 1961 DCS renewal Brass cap in good condition.  
All previous BTs are down or are stumps per record.  
New - 11" dia. Hemlock scribed "1/4 S34 BT" bears N.68°E. 10.3'  
12" dia., Fir scribed "1/4 S33 BT" bears N.15°W., 3.5'  
6 ft. steel post is set 2 ft. north

cont.

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2875, surveyed Aug. 2017/Feb. 2019- (DCSO records Vol. 59 Page 23641-2)

-----

The ¼ sec. cor. of secs. 33 & 34, perpetuated by Godfrey, in 1961; subsequently perpetuated by Douglas County Surveyors Office, in 1977; further perpetuated by Edwards, in 2011; monumented with an iron post, 1¼" dia., firmly set, projecting 16" above ground, with a brass cap (properly) mkd. from which the remains of an original bearing tree

A hollow, decayed cedar stump, 36" dia., bears N.31°W., 7.3 ft., no marks visible.

and the remains of the bearing trees mkd. by Douglas County Surveyors Office, in 1977

A roothole bears S.77°E., 36.0 ft., alongside of which is a down fir, 21" dia., with a healed blaze.

A sawed, decayed cedar stump, 42" dia., bears N.71¾°W., 41.9 ft., with a healed blaze and a bridge spike loosely set in center of stump.

and the remains of the bearing trees mkd. by Edwards

A hemlock snag, 12" dia., bears N.70¾°E., 10.6 ft., with scribe marks ¼ S34 BT visible on partially healed double blaze.

A fir, 15" dia., bears N.15¼°W., 3.4 ft., with a healed blaze.

and a new bearing tree

A hemlock, 10" dia., bears N.66°E., 62.5 ft. mkd. ¼ S34 BT Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center & each corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument.