

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Cut cross "X", 3"x3" on top of lower part of bridge railing at NW cor. of Hwy. bridge. X bears S.59 3/4°E., 112.0 ft. from 1/4 corner.
2 nails in "^" in brace pole (6-76A 77A) bears S.63°W., 53.5 ft.
2 nails in "^" in power pole (DE 73) bears N.68 1/2°W., 139.0 ft.
Corner falls in field 27 ft. N. of N. Hwy. R/W fence. Set steel fence post alongside brass cap at corner. Set 3/4" rod in R/W fence South 27.0ft. from corner.

Corner found and used in BLM resurvey by Donald Beck, 1963, under Contract #517 (DCSO records, Vol. 32 Page 13454)

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 9/18/2007 - C.S. File 67/24-19

Found - 2 1/2" dia., brass cap properly mkd. on 1 1/4" O.D. iron pipe, projects 8" above ground. 1961 mon.
1" dia., iron rod, 2" below ground level bears N.5 1/4°E., 1.75 ft. 1949 mon.
1/2" iron pipe not fd. 1928 mon.
Brace pole 6-76-77A with 2 nails forming a point bears S.63°W., 53.5 ft. meas. to point of nails. (Pole leans, agrees with rec. when meas. to point formed by nails) 1961
Power pole DE 73, nails missing, bears N.68 1/2°W., 139.0 ft. meas to side center (agrees w/rec) 1961
16" now 38" dia., Locust no marks visible bears N.87 1/2°W., 455.1 ft. (rec. N.88°20'W., 455.1 ft.) 1928 BT.
3/4" IR in R/W fence now bent northerly, plumb position on IR bear South, 27.0 ft. (Agrees w/rec.) 1961
"X 1/4" in old bridge wig wall not fd. 1928
3"x3" X in bridge gone, bridge now replaced by culvert 1961
New - 18" dia., ash, double blazed & scribed "1/4 S10 CS BT" bears N.2 1/2°W., 308.6 ft.
Note - Corner lies in pasture as in 1961
Compass decl. 16 1/4°E.