

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 500144

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. section 34 only

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Wilford N. Haines - Field Book H-107 (no date)
¼ cor sect. 34
12" D.Fir S.33°W., 70.8 ft.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - Aug. 16, 1961 - C.S. File 49/143

Corner Report Only
Found - Haines "T" iron and cap for E. ¼ sec. 34.
14" Fir S.32°W., 70.8 ft. scribed "¼ S34 BT"

James A. Branch - For: U.S. National Bank - May 4, 1992 - C.S. File 63/138 and M 115-23

Found - Typical Haines "T" Iron with brass washer in mound of stone. T-Iron was set in 1958 during field survey in notes on file with the DCSO as H-107.
27" Fir with BT tag mkd. "Haines 1958" bears S.31°15'W., 70.0 ft. (Rec. 7" Fir S.33°W., 70.8 ft.)
New BTs -16" Fir scribed "¼ S34 BT" bears S.76°W., 29.8 ft.
17" Fir scribed "¼ S34 BT" bears S.45°45'W., 32.4 ft.
27" Fir set by Haines, bears S.31°15'W., 70.0 ft.
7" Fir scribed "¼ S34 BT" bears S.28°45'W., 31.3 ft.