

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1437)

Set post cor. of secs. 11, 12, 13 and 14, from which
A Fir 40" dia., bears N.40°W., 54 lks. dist.
A Fir 6" dia., bears N.22°E., 8 lks. dist.
A Fir 12" dia., bears S.42°E., 54 lks. dist.

O.F. Thiel - For: Vernon Goodrich and Morningstar Estate - Aug. 1944 - Field Book 118 Page 21

At sec. cor., drove 2" Pipe.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones and W. Penley, crew - Feb. 13, 1968 - C.S. File 49/143-98

Found - 2" Iron pipe at sec. cor., tied from survey C.S. File 43/142 and M 10-38
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 6 W
S 11 | S 12
S 14 | S 13
1968
New BTs -8" D.Fir N.34°E., 31.3 ft. mkd. T22S R6W S12 CSBT
28" Maple N.25°W., 49.7 ft. mkd. T22S R6W S11 CSBT
11" D.Fir S.50°W., 71.7 ft. mkd. T22S R6W S14 CS BT
Power Pole #6-54 S.59°E., 19.9 ft. PK nail in base of pole.
(DCSO notified July 16, 1974 that the 28" Maple will be cut. Stump with scribing intact.)

Fd. OK, March 1990, M 109-74
Fd. 2" iron pipe, (no cap) Feb. 1999 by J. Branch - M129-33

Bruce Shaner - 11/16/1999 - C.S. File 65/23-17

Found - 2" iron pipe & bent 1" iron pipe.
Brass cap gone & needs replacement, from which:
24" D.Fir BT (rec. 8") face overgrown, bears N.34°E., 31.3 ft.
24" D.Fir BT (rec. 11") face overgrown, bears S.50°W., 71.7 ft.
Maple BT & power pole gone.
Note - BC needs replacing.
Section corner is at end of newly rocked road in RV Camp (small & new). A N-S fence line is East some 50 ft. ±.

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 11/29/1999 - C.S. File 66/12-44

Found - 2" I.D. iron pipe flush with ground, 1944
1" I.D. protrudes 15" Above ground bent, brass cap
is gone. 1968 DCSO
No OBTs found
1968 Maple now gone
8" now 29" dia., D.Fir with a fully healed single
blaze bears N.28½°E., 31.3 (rec. N.34°E., 31.3
ft) 1968
11" now 21" dia., D.Fir with a fully healed double
blaze bears S.45°W., 71.7 ft. (rec. S.50°W., 71.7
ft) 1968
Set - 5/8" by 30" long iron rod in center of a 2" I.P.
with DCSO alum. cap stamped "1999" flush with
ground.
24 ft. x 18 ft. conc. pad chisel a 3" "+" midway
between the NE & NW corners on north edge of
conc. pad. "+" bears S.21½°W., 33.1 ft.
Power access panel pole bears N.14°W., 73.3 ft.
1968 I.P. removed, survey point falls in private
camp ground.

**NOTE - Position of corner not set by double proportionate
measurement. See FB 118 Pg. 21**

Fd. Alum. cap, 2 BOs & 2BTs by Carl Sweeden, 1/2006 - M151-35