

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 1 and 2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1439)

-----  
Set ¼ sec. post, from which  
A W.Oak 30" dia., bears N.45°E., 172 lks. dist.  
A Fir 8" dia., bears S.58°W., 72 lks. dist.

Douglas Co. Surveyors Office - Larry E. Monrean and T.R. Plouff, crew - Wit: Robert G. Dean and Don Churchill - Aug. 27, 1981 - C.S. File 61/27-34

-----  
Found - 30" dia. stump, decayed (orig. 8" Fir). We open stump and find good scribing "BT".  
Other orig. BT not found.  
Set Brass cap on a 1" x 30" I.P. set at record bearing and distance of found orig. BT, (tree bearing S.58°W., 47.5 ft.), stamped "Douglas County Surveyor T22S R6W ¼ S2 S1 1981", set 22" in ground.  
New BTs -18" W.Oak blazed and scribed ¼ S1 CS BT bears S.17°E., 7.5 ft.  
13" W.Oak blazed and scribed ¼ S1 CS BT bears S.72½°E., 47.9 ft.  
11" W.Oak blazed and scribed ¼ S1 CS BT bears N.52½°E., 17.5 ft.  
12" B.Oak blazed and scribed ¼ S2 CS BT bears N.0½°W., 34.3 ft.  
Fence corner S.48½°W., 30.0 ft. Fence running N-S-E.

Robert Dean - For: Don Churchill - Aug. 28, 1981 - M 88-65

-----  
Set 1/2" x 24" Iron rebar, from which  
A rotted 30" Fir stump "BT" visible at base of 8" pitched core, bears S.59°05'W., 47.52 ft. (Rec. S.58°W., 47.52 ft.) The bearing is oriented to the South 1/2 mile of the section line and matches the compass bearing by the DCSO.  
A 1" galv. I.P. with 2½" brass cap by the DCSO 1981, bears S.59°W., 2.32 ft.  
An old fence bears West 25 ft.  
An old fence bears South 21 ft.

Douglas Co. Surveyors Office - L.E. Monrean, Deputy, T.R. Plouff, crew - Sept. 8, 1981 - C.S. File 61/27-36

-----  
It was pointed out by R.Dean, L.S. #1808, that a measuring error was made on our previous visit while setting brass cap monument from found BT stump. The following is an account of our correction procedure. (Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. secs. 1 and 2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Found - A DCSO brass cap monument set 8/27/81.  
A 1/2" x 24" I.R. set by Dean. (M 88-65)  
A check of the orig. bearings and distance to the found BT stump agrees with the position of the 1/2" I.R. set by Dean to mark the true quarter corner position.

Set - We Remove the 1" x 30" I.P. with attached brass cap and replace it with a 5/8" x 30" I.R. with attached alum. cap  
We SET the I.P. monument at the true quarter corner position; cap mkd. "Douglas County Surveyor T22S R6W ¼ S2 S1 1981" Set found 1/2" x 24" I.R. along South edge of brass cap monument, from which

- The orig. 8" Fir now 30" dia. Fir stump scribed "BT" bears S.58°W. 47.5 ft.
- The 5/8" x 30" I.R. with alum. cap (set to mark old position of cap), bears S.58°W., 2.3 ft.
- A W.Oak 18" blazed and scribed "¼ S1 CS BT" bears S.0½°E., 8.3 ft.
- A W.Oak 13" blazed and scribed "¼ S1 CS BT" bears S.70°E., 46.6 ft.
- A W.Oak 11" blazed and scribed "¼ S1 CS BT" bears N.52°E., 15.4 ft.
- A B.Oak 12" blazed and scribed "¼ S2 CS BT" bears N.2½°W., 33.1 ft.

Fence cor. bears S.50°W., 32.6 ft. Fence lines run North, South and East.

Fd. OK by H. Christensen, Oct. 2004 - M145-69