

PRIMARY CORNER DESCRIPTION Sec Cor for 1 & 12; 6 & 7, 22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1385)</p> <p>-----</p> <p>Set post cor. of secs. 1, 6, 7, and 12, from which A W.Oak 6" dia., bears N.4°E., 168 lks. dist. A W.Oak 8" dia., bears N.40°W., 216 lks. dist. Raised monument of stone.</p>																				
<p>Oscar F. Thiel - For: Ray B. Ritchey - Dec. 4, 1906 - C.S. File 64/48 page 8</p> <p>-----</p> <p>Set a stone 16 x 16 x 6 inches. NW tree gone. Corner stands on S. slope.</p>																				
<p>O.F. Thiel - For: Harry Haines - Jan. 1931 - Field Book 116 Page 51</p> <p>-----</p> <p>At SW cor. of sec. 6, both old trees gone. Found marks on NE. log. There seems to be a difference in the bearing and distances of the old trees. (Rock corner)</p>																				
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and Clete Putnam, crew - Oct/Nov. 1961 - C.S. File 49/143-91 & 93</p> <p>-----</p> <p>Found - Rock monument at corner. Pieces of rotted Oak wood, N.4°E., 101 or 102 ft. (govt. notes call for Oak tree N.4°E., 110.0 ft.) Logging road runs just North of Oak fragments. No stump hole visible. W. Haines states that he has seen scribing there several years ago. He couldn't remember whether or not the tree was standing at the time.</p> <p>Set Brass cap at cor. mkd: County Surveyors Office</p> <table style="margin-left: auto; margin-right: auto;"> <tr> <td></td> <td></td> <td>T 22 S</td> <td></td> <td></td> </tr> <tr> <td></td> <td>S 1</td> <td> </td> <td>S 6</td> <td></td> </tr> <tr> <td>R6W</td> <td>S 12</td> <td> </td> <td>S 7</td> <td>R5W</td> </tr> <tr> <td></td> <td></td> <td>1961</td> <td></td> <td></td> </tr> </table> <p>New BTs -16" Fir N.16°W., 46.5 ft. mkd. T22S R6W S1 CS BT. 4" Fir N.39°E., 21.0 ft. mkd. S6 CS BT. 12" Fir S.65°W., 9.4 ft. mkd. T22S R6W S12 CS BT. 7" Fir S.70°E., 16.5 ft. mkd. T22S R5W S7 CS BT. E and W fence is 2.5 ft. North of corner. 1¼" pipe bears N.88°E., 14.43 ft.</p>			T 22 S				S 1		S 6		R6W	S 12		S 7	R5W			1961		
		T 22 S																		
	S 1		S 6																	
R6W	S 12		S 7	R5W																
		1961																		
<p>Fd. OK, June 1965, B.Rogers. C.S. File 53/101-15 Fd. OK, Aug. 1981, R.Dean, M 88-65 Fd. Ok by H.Christensen, Jan. 1995 - M 123-34 Cont. next page</p>																				

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 700600

PRIMARY CORNER DESCRIPTION SEC COR FOR 1 & 12; 6 & 7 T22-5

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Fd. OK by J. Branch, Feb. 1999 - M129-33

BLM Dependent resurvey by A. Bert Skeesick & Timothy J. Moore, Cadastral Surveyors & Robert H. Browning, Surveying Technician under Group No. 2133 surveyed April/May 2006 - (DCSO records Vol. 55 Page(s) 21715-16)

The cor. of secs. 1, 6, 7, and 12, on the W. bdy. of the Tp., perpetuated by Thiel, in 1906 and 1931, from original evidence no longer in existence, remonumented by Godfrey, in 1961, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd. from which the remains of bearing trees mkd. by Godfrey

A fir, 12" dia., bears N.37°E., 20.7 ft., with a healed blaze.

A fir, 20" dia., bears S.71¼°E., 16.7 ft., with a healed blaze.

A fir, 24" dia., bears S.63°W., 8.9 ft., with a healed blaze.

A sawed fir stump, 26" dia., bears N.16°W., 46.5 ft., with a healed blaze.

and a new bearing tree

A fir, 14" dia., bears N.29¼°W., 12.0 ft., mkd. T22S R6W S1 BT.

DCSO-GIS Corner visitation - 10/31/2005 - Typed: 1/13/2011 - C.S. File 67/33-1

Monument - 1¼" IP w/BC Comments -3 Live BTS