

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 103100

PRIMARY CORNER DESCRIPTION NW cor. S. 6, T23-7; NE cor. S. 1, T23-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1497)

-----  
Set post cor. of T23S Rs. 7 and 8 W., from which  
A Fir 12" dia., bears S.42°W., 6 lks. dist.  
A Fir 20" dia., bears S.65°E., 15 lks. dist.

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 (DCSO records Vol. 6 Page(s) 2457)

-----  
At the post, which is the established corner to township 23 South in Ranges 7 and 8 West, on the 5th standard parallel South. The witness trees all standing, viz:  
A Fir 12" dia., bears S.42°W., 6 lks. dist.  
A Fir 20" dia., bears S.65°E., 15 lks. dist.

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13669-70)

-----  
At the stan. cor. of Tps. 23 S., Rs. 7 and 8 W., determined at record bearing and distance from the original bearing trees:

A sawed and burned Fir stump 26" dia., bears S.65°E., 15 lks. dist. with scribe marks T23S R7W SC visible on opened blaze.  
A sawed and decayed Fir stump 28" dia., bears S.42°W., 6 lks. dist., with a healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

S 1	S 6
R 8 W	R 7 W
T 23 S	
S C	
1964	

from which a new bearing tree and a reference monument:

A Fir 20" dia., bears S.42°E., 109 lks. dist. mkd. T23S R7W S6 SC BT.

An iron post 28" long, 2 1/2" dia., set 22" in the ground for a reference monument, bears S.20°W., 130 lks. dist., with brass cap mkd. T23S R8W S1 SC RM 1964 and an arrow pointing to the corner.

continued next page

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 103100

PRIMARY CORNER DESCRIPTION NW cor. S. 6, T23-7; NE cor. S. 1, T23-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Daniel Baker - For: Eagles View Management Co. Inc. - 12/2018  
- M175-28A-C

-----  
Found - 3¼" BLM brass cap "1964"  
36" Fir stump, S.66°E., 9.5' to center (rec S.65°E.,  
15 lks.)-Orig. BT  
36" Fir, S.37°E., 71.6' to center (rec. S.42°E., 109  
lks.)-1964 BLM BT  
32" Fir stump, S.49°W., 4.1' to center (rec S.42°W.,  
6 lks.)-Orig. BT  
3¼" BLM brass cap "1964" mkd "RM", S.23°W., 85.15'