

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1509)

Set post cor. of secs. 16, 17, 20 and 21, from which
A W.Oak 8" dia., bears N.37°E., 217 lks. dist.
Raised mound with trench, as per instructions.

Field Book 17 Page 5 (probably Roberts or Germond)

I reset as follows:
Red Fir tree 16" (cor. tree) mkd. in place.
R.Fir 10" dia. N.59°E., 16 lks.
R.Fir 13" dia. S.26°E., 23 lks.
R.Fir 13" dia. S.53°40'W., 34 lks.
R.Fir 10" dia. N.40°45'W., 34 lks.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - March 1962 - C.S. File 52/14-116

Found - Old Fir stump, scars on SE, SW, NW and NE, found scribe mark "S" on SE face.
Badly rotted Fir stump S.26°E., 15.2 ft. cut open and found scribing "T22S R7W S".

(These trees called for in old renewal by Roberts (?) 1904-08 ? See Field book #17 Pg. 5)

Fir roots N.59°E., 10.6 ft.
Stump hole S.54°W., 22.4 ft.
Stump hole N.40 3/4°W., 22.4 ft.
No trace of original bearing trees.

Set WIT. COR. 4 ft. North of corner stump. Set Brass cap mkd:

County Surveyors Office
W.C. S17|S16 4 ft. S. to corner
 S20|S21
 1962

New BTs -18" D.Fir S.5°E., 146.3 ft. mkd. T22S R7W S21 CS BT
17" D.Fir S.47°W., 116.6 ft. mkd. T22S R7W S20 CSBT
6" W.Oak N.48½°W., 114.4 ft. mkd. T22S R7W S17 CSBT
18" D.Fir N.14°E., 204.2 ft. mkd. T22S R7W S16 CSBT

Fence corner bears East 3 ft. from stump corner-fences E & S.

Fd. OK, May 16, 1989, L. Roberts, C.S. File 63/91 & M 108-22

Fd. OK, April 1994, D.Bentz, Partition 1994-0053