

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Dep. Surveyor under contract # 152
survey dated June 3, 1871 (DCSO records Vol. 4 Page 1525)

Set post cor. to secs. 4, 5, 8 and 9, from which
A Fir 30" dia., bears N.10°E., 30 lks. dist.
A Fir 40" dia., bears S.50°E., 11 lks. dist.
A Fir 36" dia., bears S.20°W., 9 lks. dist.
A Fir 30" dia., bears N.60°W., 48 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V.
Tracy and C. Putnam, crew - March 1962 - C.S. File 52/14-128

Found - Fir tree, now 54" N.3°E., (instead of N.10°E.) 19.8
ft. Faint bark scribing visible in charred bark
"S4 T22S"
Fir tree, 38" S.15°W., (instead of S.20°W.) 5.9 ft.
Faint bark scribing visible "S8 T2"
Fir tree, now 56" N.70°W. (instead of N.60°W.) 31.7
ft. slope dist. No scribing found, cruisers marks
nearly cover side facing corner.
40" Fir S.50°E., 7.3 ft. is uprooted and down and
almost completely buried in dirt and debris.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 7 W

S 5 | S 4

S 8 | S 9

1962

Rescribe-54" Fir N.3°E., 19.8 ft. bark scribe T22S R7W S4 CS
- BT in wood.

38" Fir S.15°W., 5.9 ft. scribed in wood T22S R7W S8
CS BT.

New BT - 10" R.Cedar S.17°E., 39.7 ft. mkd. T22S R7W S9 CS BT

David Edwards - For Seneca Jones Timber Co- 11/2004 - M145-72

Found - Brass Cap

54" fir snag, N.3°E., 19.8'

New - 10" fir S.1°W., 40.9', scribed "S8 BT"

6 Ft. steel post 2 ft. North & 30 ft. East.

Harvey Christensen - For: Seneca Jones Timber Co. - Aug. 2006
- M151-45

Found - 2.5" 1962 DCSO BC, .3 above ground, leaning East,
tied base of pipe

20" D.Fir N.60°W., 9.1 ft., healed face, 5' stump

19" D.Fir S.61°W., 17.7 ft., healed face.

continued next page

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd BT tags reversed for these 2 BTs, R&R tags to correct trees.
11" D.Fir, S.25°E., 15.4 ft., scribing visible,
(incorrect for section corner)
6" steel post 0.5' north