

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 4 Page(s) 1549)

Point for ¼ sec. cor. falls on a rock, in place, 18x12x12 ins., above ground, on which I
Cut an (X) at exact point for ¼ sec. cor. mkd. ¼ W of cross, from which

A Hemlock 12" dia., bears S.73°E., 35 lks. dist. mkd. ¼ S BT.

A Fir 36" dia., bears S.82°W., 47 lks. dist. mkd. ¼ S BT.
This cor. is on the S. slope of spur, 200 ft. below top.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - 1962 - C.S. File 52/14-100

Found - "X" on rock outcropping as corner, "¼S" chiseled on rock South of X.

Fir, now 48", S.82°W., 30.0 ft. (not 31.0 ft.) shows good scars. Tree alive but in poor condition.

No trace of SE BT.

New BTs -6" Hemlock N.56°E., 8.2 ft. mkd. ¼ S4 CS BT.

17" W.Fir S.20°W., 4.9 ft. mkd. ¼ S5 CS BT. (on very steep South slope 160 ft. North of creek.)

Found OK by T. Baker, Jan. 2003 - M141-58

Found Ok by D. Edwards, Nov. 2004 - M145-72