

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33, T21-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 632-633)

Set post cor. of secs. 4, 5, 32 and 33; from which
A Fir 36" dia., bears N.65°E., 6 lks. dist.
A Fir 40" dia., bears S.45°W., 43 lks. dist.
A Fir 30" dia., bears N.25°W., 44 lks. dist.
A Redwood 40" dia., bears S.30°E., 22 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664 dated May 23, 1896 (DCSO records Vol. 4 Page(s) 1548-49)

The cor. of secs. 4, 5, 32 and 33; post decayed; some of the bearing trees down; I reestablish this cor., at same point, as follows:

Set a sandstone 14x14x12 ins., 9" in the ground, for cor., mkd. with 4 notches on E. and 2 notches on W. edges; from which

- A Fir 36" dia., bears N.60°E., 21 lks. dist. mkd. T21S R7W S33 BT.
- A Cedar 30" dia., bears S.30°E., 21 lks. dist. mkd. T22S R7W S4 BT.
- A Fir 40" dia., bears S.45°W., 43 lks. dist. mkd. T22S R7W S5 BT.
- A Maple 6" dia., bears N.57°W., 40 lks. dist. mkd. T21S R7W S32 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy and crew - July 10, 1962 - C.S. File 52/14-99

Found - Fir, now 60" S.45°W., 28.4 ft., chopped open and found good scribing on old face.
Badly burned Cedar snag S.30°E., 14.0 ft. No scars or scribing found.
Fir snag, N.55°E. (not N.65°E) 4.0 ft. Shows very old axe marks on bark, no scribing found.
No trace found of orig. Fir BT to NW. No trace found of Nicklin's NE or NW BTs.
No trace of rock set by Nicklin.

Set Brass cap at cor. mkd: County Surveyors Office
S 32 | S 33 T21S R7W
S 5 | S 4
1962

New BTs -10" Hemlock N.63°W., 11.1 ft. mkd. T21S R7W S32 CSBT
6" W.Fir S.34°W., 14.3 ft. mkd. T22S R7W S5 CS BT.
5" Hemlock S.23°E., 14.2 ft. mkd. T22S R7W S4 CS BT.
32" D.Fir N.65°E., 57.2 ft. mkd. T21S R7W S33 CS BT.

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33, T21-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Cor. Fd. and used in BLM resurvey by Floyd Brooks and James Jelley, Group #'s 350 & 536, surveyed May/June 1964 (DCSO records, Vol. 32 Pages 13509-10)

Ted Baker - For: Seneca Jones Timber Co. - 1/2003 - M141-58

Found - 1962 2½" Douglas Co. brass cap.
60" Fir stump, S.45°W., 28.4 (scribe vis)
14" Hemlock, S.23°E., 14.2' (scar vis)
36" Fir N.65°E., 57.2' (scar vis)
New BT - 12" Fir, N.82°W., 27.3'
Note - All BTs are scribed & painted red, distances to BTs are center measure.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2500, Surveyed May 2012 - DCSO records BLM Plat 2013-1, T22-7 and Vol. 58 Page(s) 22975

The cor. of secs. 5, 6, 31, & 32, on the N. bdy. of the Tp., monumented with an iron post, 2½" dia., firmly set, projecting 5" above ground, with brass cap (properly) mkd. from which the remains of BTs mkd. by Brooks and Jelley
A fir, 18" dia., bears N.63½°E., 12.3 ft., with a healed blaze.
A fir, 22" dia., bears S.73°E., 13.9 ft., with a healed blaze.
A sawed, decayed fir stump, 13" dia., bears S.36¼°W., 10.9 ft.. with a healed blaze.
A fir, 42" dia., bears N.5°W., 26.4 ft., with a healed blaze.
and a new bearing tree
A fir, 4" dia., bears S.74¼°W., 28.6 ft., mkd. X BT.
Latitude 43°41'35.74"N. Longitude 123°32'41.14"W.
(NAD 1983 (CORS 96))

Fd. OK 4/2018 by R. Quimby C.S. File 65/101-9