

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 308100

PRIMARY CORNER DESCRIPTION Standard cor. for 4 & 5 only, T23-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1496)

Set standard cor. to secs. 4 and 5, from which
A B.Oak 20" dia., bears S.13°E., 143 lks. dist.
A B.Oak 12" dia., bears S.46°W., 368 lks. dist.

John H. Markham, Jr. - Wit: Geo. & Wm. Vaughn and Bob Blair
-March 31, 1951 - ~~(No record source found)~~ C.S. 40/303-1
(7/3/2024)

Determined by O.B.T., A B.Oak stump hole bears S.13°E., 94.0 ft. dist.
At corner point, Set 1" x 24" Iron pipe, from which
A B.Oak 7" dia., bears S.46°W., 23.0 ft. mkd. S5 BT.
A Laurel 9" dia., bears N.87°E., 63.5 ft. mkd. S4 BT.

Pipe in N & S fence, 21 ft. S. of fence cor., E., W., & S., per Godfrey, 1962 - Written on previous corner renewal pgs.

DCSO fd ok March 1, 1962 Milo Godfrey C.S. File 52/14-13 (added 3/21/2018):
FD. Markham's renewal on Twp line. Fd. 1" iron pipe in N & S fence line.
Fd. B.Oak (now 16" dia.) S.46°W., 23.0 ft. Shows good upper scar & "BT" scribed in bark below.
No trace fd of orig. BTs.

Corey M Woodruff - For: Elkton Reserve, LLC & the USA - 1/2012 - M163-30A-C

Found - 1" IP set by Markham in fenceline
BT FD - 21" Oak brs. S.46°W., 23.0'
BT mkd- 18" D.Fir brs. S.16°E., 48.4'