

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1529)

Set ¼ sec. post, from which
A Fir 5" dia., bears N.62°W., 9 lks. dist.
A Fir 5" dia., bears S.45°E., 17 lks. dist.

Wilford N. Haines, #239 - For: Woolley Logging - April 1861 -C.S. File 51/191 and M 38-69; AND June 29, 1962 - C.S. File 51/222-5

Set corner at point halfway between section corners.
Set 1" x 1" x 36" T. Iron for ¼ corner.
Scribed - 8" D.Fir N.23½°E., 10.6 ft.
Drove bridge spike in 4½ ft. stump S.18°E., 13.0 ft.

Cor. Fd. OK, June 1962, DCSO, M. Godfrey, C.S. File 52/14-12

Douglas Co. Surveyors Office - Gary L. Langlitz; Karen Cheney, crew - Nov. 2, 1976 - C.S. File 59/26-1

Found - An 8" now 16" D.Fir, alive and well with healed double blaze bears N.23½°E., 10.6 ft.
A 54" D.Fir stump with bridge spike driven in the center bears S.18°E., 13.0 ft.
We do not find the "T" iron set by Haines.

At the corner point as determined by the record measurements to the above mentioned bearing trees:

Set set a 1" x 30" Iron pipe, 26" in the ground with brass cap attached:

Douglas Co. Surveyor
T 22 S R 7 W
¼ $\frac{S\ 28}{S\ 33}$
1976

New BT - A 7" D.Fir bears S.51°W., 5.9 ft. scribed "¼ S33 CS BT" on a double blaze.

A 5/8" iron rod bears S.47°E., 3.35 ft. Our records indicate a 5/8" I.Rod as being found at the ¼ corner in 1974 (See M53-42A), but no indication is made concerning when the 5/8" I.R. was set.

This corner is located approx. 100 ft. N.20°W., of a Cascade Utilities Transmitter.

continued next page

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, under Group #1797, surveyed April/June 1996 - (DCS0 records Vol. 52 Page(s) 20168-9)

The ¼ sec. cor. of secs. 28 & 33, reestablished by proportionate measurement by Haines, in 1961, this position was perpetuated by Langlitz, Deputy County Surveyor, in 1976. There is no remaining evidence of the original corner, therefore this position is accepted as the corner; monumented with an iron post, 1½" diam., firmly set, projecting 4" above ground, with brass cap mkd.

DOUGLAS CO. SURVEYOR

T 22 S

R 7 W

¼ S 28
S 33

1976

from which a bearing tree and an accessory mkd. by Haines
A fir, 21" diam., bears N.23 ¾°E., 15½ lks., with healed double blaze.

A bridge spike, set flush in the center of a rotted sawed fir stump, 61" diam., bears S.17½°E., 19½ lks.

and the remains of a bearing tree mkd. by Langlitz

A rotted fir stump, size indeterminate, bears S.58°W., 11 lks., no marks visible.

and an accessory set by person(s) unknown and recorded by Langlitz

A rebar, 5/8" diam., firmly set, projecting 7" above ground, bears S.45½°E., 5 lks.

and a new accessory and bearing tree

The NW. cor. of a chain link fence, bears S.35¼°E., 42 lks., fence extends E. and S.10°W. (fence is part of the Cascade Utilities transmitter site.)

A fir, 6" diam., bears S.26°W., 147 lks., mkd. ¼ S33 BT. Corner is located in a woven wire fence extending E. and W.