

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1512)

Set ¼ sec. post, from which
A Fir 30" dia., bears S.16°E., 145 lks. dist.
A Fir 36" dia., bears N.51°E., 143 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1521)

Set ¼ sec. post, from which
An Oak 8" dia., bears N.10°E., 100 lks. dist.
An Alder 8" dia., bears S.15°W., 28 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy and C. Putnam, crew - March 1962 - C.S. file 52/14-123

Found - Fir snag now 78", N.51°E., 94.4 ft., no scribing found, but old axe marks in badly burned bark.
Old Fir log, almost completely buried in swampy ground, bears S.16°E., 95.7 ft.

Position checks call from wit. cor. (Gordon & Gardner) on bank of Elk Creek, East of ¼ corner. Also checks tie shown on map of State Hwy. No. 38.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 7 W
1855 ¼ $\frac{S\ 15}{S\ 22}$
1962

New BTs -12" D.Fir S.50°E., 16.7 ft. mkd. ¼ S22 CS BT.
8" D.Fir N.28°E., 19.6 ft. mkd. ¼ S15 CS BT.

Cor. Fd. and used by Jelley and Beck in BLM resurvey, under Group #590, surveyed July/Sept. 1965 (DCSO Records Vol 33 Page 13959)

Fd. OK, Feb. 1987, J. Hollingsworth, C.S. File 63/62

Fd. Brass cap, July 1992, O.D.O.T., M 115-38
Fd. OK, March 1998 by G. Riley - M 128-33
Fd. Ok by Ken Hoffine - June 2006 - M151-22