

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 042040

PRIMARY CORNER DESCRIPTION NW Cor. Edward Griffin DLC #42

Alias <u>043010</u>	Description <u>NE Cor. Wm. Helbert DLC #43</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,  
dated Sept. 1856

-----  
At the NW cor. on left bank of Umpqua River in Sec. 22, Set  
post, from which

An Oak 15" dia., bears S.87°W., 70 lks.

An Oak 15" dia., bears S.26°W., 215 lks.

-----  
Jesse Cole, Deputy - 1915 - Vol. 2 Page 210; Field Book 40  
Pages 29 & 30 (and "old" cor. book, page 25)

-----  
Set an Oak post 4" x 4" x 3½ ft. marked C.S. Cl. 43, from  
which original BTs bear as follows:

An Oak, originally 15" dia. with blaze scar nearly rotted  
away, bears N.64°W., 70 lks. dist.

An Oak, originally 15" dia., cut out scar and scribe marks  
plainly visible, S.55°W., 215 lks. dist.

-----  
Ben B. Irving, Co. Surveyor - Milo Godfrey, Witness - March  
1945 - M 10-72

-----  
Found - Post set by Cole in 1915 has disappeared.

OBT, N.64°W., 70 lks. entirely rotted away except  
for roots.

OBT, Oak 15" dia., S.55°W., 215 lks. has been cut  
and stump nearly rotted away, chopped out BT  
blaze and found scribe marks "BT" thereon.

Set a 1/2" x 72" Iron pipe 70" in the ground for the cor.

Marked a new bearing tree,

A W.Oak 24" dia., which bears S.59°W., 42.3 ft.

An Ash 24" dia., which bears N.87°W., 65.3 ft. "NW  
Cor. DLC 42 CS BT"

-----  
Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike  
Stone & Wm. Stoffel, crew - Sept. 1964 - C.S. File 52/14-86

-----  
Found - 1/2" I.P. set by Irving in 1945. Pipe buried approx.  
1 ft. deep in sand.

Stump of W.Oak S.59°W., 42.3 ft., shows very plain  
"BT" scar, did not open. Stump recently cut.

Stump hole and rotted remains of Ash, N.87°W., 65.3  
ft. Trunk buried in sand.

New BTs -13" Maple N.47°W., 4.5 ft. mkd. NE DLC 43 CS BT.

14" Maple S.5°W., 30.8 ft. mkd. NE DLC 43 CS BT.

No trees near East of line.

Iron pipe is at North end of N. and S. fence line.

CONT.

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 042040

PRIMARY CORNER DESCRIPTION NW Cor. Edward Griffin DIC #42 Wit. cor

Alias 043010 Description NE Cor. Wm. Helbert DIC #43

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Corey M. Woodruff - For: Eagle's View Management - 10/2016 - M172-73

-----

Found - IP set per M10-72 not found , appears to have been destroyed by the river. The position for this corner was determined by holding record bearing & distance from the fd. maple BT that was mkd by C.S. 52/14. The ground at the corner's location is not stable, a witness corner was set.

Set - 36" Maple bears S.5°W., 30.80 from rec. position.  
¾" iron rod with 3" alum. cap mkd "STUNTZNER ENGINEERING" for witness corner. From which:  
A 5/8"x30" iron rod with Yellow plastic cap mkd "STUNTZNER ENG" bears S.40°31'18"W., 49.00'  
A 5/8"x30" iron rod with Yellow plastic cap mkd "STUNTZNER ENG" bears S.44°10'56"E., 27.20'