

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 044120

PRIMARY CORNER DESCRIPTION Int. SE cor. Wm. Hathaway DLC #44

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated Sept. 1856

Marked an Oak 8" dia., for interior corner, from which
An Oak 12" dia., bears S.88°W., 31 lks.
A Fir 12" dia., bears S.2°E., 73 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Feb.
1955 - C.S. File 46/125 and M 8-18

Location of corner established by proportional measurement.
No evidence of "L" corners found - the call for creek checks.
Set an Iron pipe with brass cap at corner point mkd: Co.
Surveyors Office, 1955, Int L CL 44 T22S R8W.
Blazed and scribed:
16" R.Fir N.38°E., 13.0 ft. mkd. Cl. 44 T22 R8 CS BT.
14" R.Fir N.25°W., 11.0 ft. mkd. Cl. 44 T22 R8 CS BT.
This corner falls @ E edge of old Co. Rd at bottom of cut bank

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike
Stone & Wm. Stoffel, crew - Sept. 1964 - C.S. File 52/14-87

Found - 18" D.Fir N.38°E., 13.0 ft., scribing visible on not
completely healed over scars.
Brass cap not found, a slide has covered portion of
road at this point. Brass cap probably buried
under logs, rocks and dirt.
No trace of NW tree mkd. in 1955, probably buried in
slide.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 8 W
Int. "L" DLC 44 | _____
1964
New BT - 15" D.Fir N.45°W., 17.3 ft. mkd. Int. L DLC 44 CS BT

Fd. OK, July 12, 1973, DCSO, V. Tracy, C.S. File 56/34

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 3/7/2007 - C.S. File 67/21-19

Found - 2½" brass cap ("properly" mkd) attached to 1¼" O.D.
iron pipe in slough of cut bank on old logging Rd. BC/IP was
leaning into Rd. with most of IP exposed. Base of BC/IP
appeared to be unmoved. We referenced position & removed. Dug
down deeper in a Northerly direction (magnetic sounding) & fd
top of 1955 BC/IP laying on side. Base of 1955 monument is
approx 40" away in a northerly direction from 1964 position.
continued next page

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 044120

PRIMARY CORNER DESCRIPTION Int. SE cor. Wm. Hathaway DLC #44

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Fd BTs - 16" now 18" dia., D.Fir fully healed double blaze visible bears N.45°E., 12.7 ft. tree appears to have slid down hill in a southwesterly direction & leans severely to the east. (Rec. N.38°E., 13.0 ft.) 1955

15" now 24" dia., x 2 ft. tall rotten stump faint healed blaze visible. Opened & fd partial scribing & axe marks. Bears N.45°W., 16.5 ft. (N.45°W., 17.3 ft.) 1964

To verify position of corner, due to sliding, we measured the dist. to the Ext. "L" Corner DLC #44 & fd. it to be 317.2 ft. (Rec. 329.25 ft. per map M8-18)

New - At the 1964 position: a 5/8"x60" iron rod with a 1½" dia., alum. cap stamped "DOUGLAS CO. SURVEYOR" is driven 48" into slough on Northeasterly edge of overgrown logging rd.

4" dia., pistol butt D.fir, double blazed & scribed "X" on high blaze and "CS BT" on low blaze, bears N.85°W., 36.1 ft.

Note - The vicinity around iron rod is believed to be in part of an active slide area. 5/8" iron rod was set to preserve approx. 1964 location
Compass decl. 16¼°E.