

PRIMARY CORNER DESCRIPTION E SE cor. Wm. Hathaway DLC #44

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated Sept. 1856

Set post for SE cor. on high ridge, from which
An Oak 10" dia., bears N.80°E., 25 lks.
An Oak 15" dia., bears N.88°W., 112 lks.

F.J. Cole, Deputy Co. Surveyor - Wit: Geo. Walker; L. Ross; C. Henderer - July 8, 1913 - Vol. 2 Page 191 and Field Book 32 Page 32

Renew corner, set stone 9" x 14" x 18", and marked
An Oak 24" dia., N.87¼°E., 128 lks. dist.
An Oak 14" dia., S.77¼°W., 154 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Feb. 1955 - C.S. File 46/125 and M 8-18

Found - 9" x 14" x 18" stone and both BTs as scribed in 1913, which check for bearing and distance. The NE BT we cut out and scribing visible, tree alive. The SW BT center rotted and all scribing gone.
Set an Iron pipe with brass cap at side of stone and blaze and scribe:
16" W.Oak S.45°E., 28.0 ft. mkd. S.E. DLC 44 CS BT.
14" R.Fir N.57½°E., 69.7 ft. mkd. SE DLC 44 CS BT.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Jan. 9, 1987 - C.S. File 62/40-1

Found - A 2½" dia. DCSO brass cap on a 1¼" O.D. Iron pipe, protruding 8" above ground.
A sandstone rock along North edge of I.P. Top measures 9" x 14", flush with ground.
15" now 14" dia. 2 ft. high broken trunk stump Oak with possible blaze scar, no scribing found, bears West 88.0 ft. (Orig. BT) (Rec. per Cole, S.88°W., 88.0 ft. see field notes) (Rec. per orig. N.88°W., 73.9 ft.)
Orig. NE BT gone.
14" now 25" dia. W.Oak with an opened rotted blaze partial reverse scribe found "S", bears S.77¼°W., 101.5 ft. (Cole BT)
24" now 30" dia. W.Oak with a fully healed single blaze bears N.87¼°E., 84.5 ft. (Cole BT)
(Cont. Next Page)

