

PRIMARY CORNER DESCRIPTION Pt. on SE bdy. DLC #49

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

(I believe Brooks was mistaken in his report of a Frear visit in 1935. DCSO records indicate BTs described were by Irving in 1941) V. Laugen, June 1995

Fd. OK by D. Edwards, Feb. 2000 - M134-20  
Found OK by D. Edwards, Mar. 2004 - CS65/51-1

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2180 & 2300, surveyed May/Oct. 2007 (DCSO records Vol. 56 Page(s) 22234)

-----

The interior cor. on the S. bdy. of DLC 49 in sec. 8, perpetuated by Irving in 1941, and remonumented by Brooks and Jelley in 1963-65; monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd.  
from which the bearing trees mkd. by Irving in 1941 and reported as marked by Frear in 1935 by Brooks and Jelley  
    A W.Oak, 23" dia., bears N.54°E., 33.7 ft., with a healed blaze.  
    A maple, 21" dia., bears S.68½°W., 52.1 ft., with a healed blaze. (Record, S.72°W.)

The Irving iron pipe, ½ in. diam., firmly set, projecting 4" above ground, reset Brooks and Jelley, is alongside the cor. From this corner, a point established by person(s) unknown, and was not utilized for control in this survey, bears S.33¾°E., 11.4 ft.; monumented with an iron pipe, 1" dia., firmly set, projecting 12" above ground.  
Corner is located on the right bank of the Umpqua River, 500 ft. wide, course S. 55° W., and SE., 40 ft., from the top of the bank and beginning of bottomlands, and NW., 40 ft., of the edge of bedrock.