

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 052010

PRIMARY CORNER DESCRIPTION N NE cor. Charles Henderer DLC #52

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated Sept. 1856

Set post NE cor. Cl. 52, from which
An Oak 12" dia., bears S.57°W., 275 lks.
An Oak 12" dia., bears N.72½°W., 330 lks.

Survey by Wilford N. Haines - For: Kenneth Gossel - June 1977
- M 66-15

Found - 12" Oak S.57°W., 275 lks., now stump.
12" Oak N.72½°W., 330 lks., now 22" Oak, down.
Found good reverse scribe.
Set 5/8" Rebar.
Property corner set 18.7 ft. East of NE DLC corner. Set 5/8"
rebar and scribed 12" Fir S.55°W., 20.7 ft.

Mark Smalley - For: Roseburg Resources - 12/2000 - M 132-59

Found - 5/8" rebar 8" exposed. M 66-15
~~12" Fir, S.55°W., 20.7 ft. rotten stump. *Not DLC BT *~~
New BTs- 16" Fir, N.32°W., 6.6 ft. "DLC 52 BT"
13" Fir, S.79°W., 16.5 ft. "DLC 52 BT"
12" Fir, S.35°W., 10.0 ft. "DLC 52 BT"
* This BT references a private property corner on M66-15 not
the DLC corner per research by DCSO & Mark Smalley 1/11/2005

DCSO-GIS Corner visitation - 12/7/2004 - Typed: 1/19/2011 -
C.S. File 67/33-1

Monument - 5/8" rebar. Comment - OK