

PRIMARY CORNER DESCRIPTION N NW Cor. John Fryer DLC #57

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Les Roberts, surveyed for Meints, Jan. 1997 - M 126-32

Found - 1963 BLM iron pipe and brass cap.
26" Fir, N.65°W., 35.2 ft. (scar vis.) 1963 BT
New Accessory -
8" Alder, N.52°E., 7.2 ft. (scribed/metal washer)

Fd. OK by R. Hendricks, Nov. 1998 - M130-77

Dependent resurvey by Edith M Forkner, Cadastral Surveyor,
under Group #2180 & 2300, surveyed May/Oct. 2007 (DCSO
records Vol. 56 Page(s) 22237-8)

The N-NW cor. of DLC 57, in sec. 9, on the S. bdy. of DLC 49,
perpetuated by Frear in 1917, and remonumented by Brooks and
Jelley in 1963-65; monumented with an iron post, 2½" dia.,
firmly set, projecting 5" above ground, with brass cap
(properly) mkd.

from which the remains of a bearing tree mkd. by Frear and
reported by Brooks and Jelley

A roothole bears N.67¼°W., 63.4 ft., alongside of which is
a down decayed stump, 19" dia., no marks visible.

and the remains of the BTs mkd. by Brooks and Jelley
A decayed fir stump, 23" dia., bears S.45¾°E., 35.3 ft.
no marks visible. (Record, S.50°E.)

A roothole bears S.37½°W., 59.4 ft., alongside of which is
a down decayed fir, 20" dia., with no scribe marks
visible on opened blaze.

A fir, 31" dia., bears N.66°W., 35.3 ft., with a healed
blaze.

and a bearing tree mkd. by Roberts in 1997
An alder, 10" dia., bears N.49½°E., 7.2 ft., with scribe
marks T22S R8W C49 BT visible on bark and a healed
blaze over a washer below the scribe marks.

The Frear iron pipe, 1½" dia., firmly set, projecting 2"
above ground, reset by Brooks and Jelley, and a steel fence
post are alongside the cor.

Corner is located on nearly level land on a generally NE.
slope.