

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 202 survey dated March 11, 1874 (DCSO records Vol. 4 Page(s) 1591)

Marked a Fir 8" dia. for the cor. to secs. 17, 18, 19 and 20, from which

- A Fir 8" dia., bears N.35°E., 28 lks. dist.
- A Fir 24" dia., bears S.38°E., 34 lks. dist.
- A Fir 7" dia., bears S.40°W., 7 lks. dist.
- A Fir 36" dia., bears N.70°W., 34 lks. dist.

GLO survey by Geo. F. Rigby, U.S. Cadastral Engineer, under Group #143, surveyed Oct/Nov. 1931 - (DCSO records Vol. 27 Page(s) 11650-51)

The cor. of secs. 17, 18, 19 and 20, is a Fir tree, 20" dia., which was squared up about 55 years ago. The overgrowth has been chopped off and fire has burned off all traces of marks. Beside the tree

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for sec. cor., with brass cap mkd:

T 22 S	R 8 W
S 18	S 17
S 19	S 20
1931	

from which

Old bearing tree:

- A Fir 60" dia., bears N.70°W., 59 lks. dist. overgrowth has been chopped away and the marks burned off; on a new blaze mark T 22 S R 8 W S18 BT.

New bearing trees:

- A Fir 30" dia., bears N.11°30'E., 57 lks. dist. mkd. T22S R8W S17 BT.
- A Fir 24" dia., bears S.52°30'E., 76 lks. dist. mkd. T22S R8W S20 BT.
- A Fir 20" dia., bears S.16°15'W., 56 lks. dist. mkd. T22S R8W S19 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon "Ray" Tracy, crew - Feb. 25, 1963 - C.S. File 52/14-53

Found - GLO brass cap set in 1931 alongside rotten Fir stump 34" W.Fir S.16¼°W., 37.0 ft., shows good scar.
Old Fir snag N.70°W., 39.0 ft., shows very plain axe scar.

Badly rotted W.Fir stump N.11½°E., 37.6 ft., no marks visible. (Cont. Next Page)

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. cor. for 17, 18, 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

D.Fir stump S.52½°E., 50.2 ft., shows good axe scar.
New BTs -8" W.Fir N.48°W., 21.2 ft. mkd. T22S R8W S18 CS BT.
15" D.Fir N.50°E., 46.0 ft. mkd. T22S R8W S17 CSBT.
7" D.Fir S.70°E., 45.9 ft. mkd. T22S R8W S20 CS BT.

Cor. Fd. and used in BLM resurvey by Brooks and Jelley, under Group #'s 514 and 350, surveyed June 1963/March 1965 - (DCSO records, Vol. 33 Pages 13702-03)

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 595 and 657 - surveyed Aug. 1965/Dec. 1967 - (DCSO records Vol. 34 Page(s) 14122)

The Sec. cor., monumented with an iron post, 2" dia., firmly set, projecting 6" above ground, with a 1931 brass cap. from which an original bearing tree

A Fir stub 65" dia., bears N.70°W., 59 lks. dist. with a healed blaze.

and bearing trees mkd. by Rigby in 1931

A burned and decayed Fir stump 30" dia., bears N.11½°E., 57 lks. dist. with no marks remaining.

A sawed Fir stump 30" dia., bears S.50½°E., 76 lks. dist. with a healed blaze. (Rec. S.52½°E.)

A sawed W.Fir stump 38" dia., bears S.16¼°W., 56 lks. dist. with a healed blaze.

and bearing trees mkd. by the County in 1963

A sawed Fir stump 15" dia., bears N.48½°E., 70 lks. dist. with a pitched over blaze.

A down Fir 9" dia., bears S.71½°E., 68 lks. dist. with fragmentary scribe marks visible on partly healed blaze

A Fir 9" dia., bears N.46½°W., 34 lks. dist. with fragmentary scribe marks visible on partly healed blaze.

and new bearing trees

A W.Fir 5" dia., bears N.22°W., 53½ lks. dist. mkd. T22S R8W S17 BT.

A W.Fir 12" dia., bears S.58°W., 70 lks. dist. mkd. T22S R8W S20 BT.

A W.Fir 5" dia., bears S.63°W., 33 lks. dist. mkd. T22S R8W S19 BT.

A W.Fir 6" dia., bears N.10 3/4°W., 48½ lks. dist. mkd. T22S R8W S18 BT.

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Rob Ward, Ward NW Inc. - Ron Rice - Ben Pastor - 11/27/2002 -
C.S. File 65/44-29

Found - 1931 GLO BC with the following accessories:
28" W.Fir bears N.46½°W., 22.4 ft. healed face.
21" W.Fir bears N.10¾°W., 32.0 ft. healed face.
5"-12"-5" White Firs are missing.
New - 10" W.Fir bears S.19°E., 10.2 ft. scribed "T22S R8W
S20 BT"
27" W.Fir bears S.66°W., 21.8 ft. scribed "T22S R8W
S19 BT"

Dependent resurvey by Edith M Forkner, Cadastral Surveyor,
under Group #2180 & 2300, surveyed May/Oct. 2007 (DCSO
records Vol. 56 Page(s) 22223-4)

The cor. of secs. 17, 18, 19, & 20, perpetuated by Rigby in
1931, by establishing a monument at record bearing and
distance from the remaining original BT and alongside the
original 1874 Byars corner tree which he found in poor
condition. The Rigby monument was accepted by Brooks and
Jelley in 1963-65, Brooks and Peterson in 1965-67, and by
private surveyors as the cor. and is accepted as the best
available evidence of the position of the original corner
tree; monumented with an iron post, 2" dia., firmly set,
projecting 8" above ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree

A decayed fir stump, size indeterminate, bears N.74½°W.,
38.9 ft., with illegible scribe marks visible on
partially healed blaze. (Record, N.70°W.)

and the remains of the BTs mkd. by Rigby and reported by
Brooks and Jelley

A decayed fir stump, size indeterminate, bears S.50½°E.,
50.2 ft., no marks visible.

A decayed fir stump, size indeterminate, bears S.16¼°W.,
37.0 ft., no marks visible.

and the remains of the bearing trees mkd. by Godfrey in
1962-633 and reported by Brooks and Jelley as being mkd. by
Fred Darby, Douglas County Surveyor, in 1963

A decayed fir stump, 15" dia., bears N.48¼°E., 46.2 ft.,
with scribe marks BT visible on open blaze. Stump is
behind a W.Fir, 1 ft. dia.

A fir, 28" dia., bears N.49°W., 20.8 ft., with a healed
blaze. (Record, N.46½°W., 22.4 ft.)

and the remains of the BTs mkd. by Brooks and Peterson

A W.Fir, 19" dia., bears N.22°E., 35.3 ft. with a healed
blaze.

continued next page

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A W.Fir stump, 36" dia., bears S.58°E., 46.2 ft., no marks visible.

A W.Fir, 28" dia., bears S.63°W., 21.8 ft., with scribe marks S19 BT visible on pitched-over, partially healed blaze and an aluminum nail on the right side center added by Ward in 2002.

A W.Fir, 22" dia., bears N.10¼°W., 32.0 ft., with a healed blaze.

and a bearing tree mkd. by Ward in 2002

A W.Fir, 21" dia., bears S.19½°E., 10.2 ft., with scribe marks R8W S20 BT and other illegible scribe marks visible on pitched-over partially healed blaze and an aluminum nail on the right side center.

An aluminum fence post is alongside the cor.

Corner is located on a SW. slope, at the NW. cor. of recently logged area, edge bears S & E, and W, 825 ft. from Hedden Ridge Road, graveled surface, 12 ft. wide, extending N.20°W. and S.35°E.