

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias	Description

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2180 & 2300, surveyed May/Oct. 2007 (DCSO records Vol. 56 Page(s) 22226-7)

The ¼ sec cor of secs 17 & 18, reestablished by Rigby in 1931, & recovered by Brooks and Jelley in 1963-65, who report recovering the Rigby monument but not remonumenting the cor; monumented with a BLM iron post, 2½" dia., firmly set, projecting 8" above ground, with brass cap (properly)mkd.

from which the remains of the bearing trees mkd. by Rigby
A decayed fir stump, size indeterminate, bears N.48¼°E., 11.9 ft. no marks visible. Stump is partially uprooted.
A decayed fir stump, size indeterminate, bears S.56°W., 21.1 ft., with scribe marks¼ S18 BT visible on detached blaze.

and the remains of the BTs mkd. by Phillips in 1954, not recorded, and reported by Brooks and Jelley

A decayed fir stump, 30" dia., bears S.61°E., 20.5 ft., no marks visible.
A fir stump, 40" dia., bears S.87°W., 77.2 ft., with partially healed axe marks. (Record, down fir.)

and the bearing trees mkd. by Brooks and Jelley
A W.Fir, 29" dia., bears N.15°E., 136.6 ft., with a healed blaze and on N. side axe marks X at head height.
A W.Fir, 22" dia., bears S.39°W., 120.8 ft., with a healed blaze. (Record, S.40°W.)

An iron rod with International Paper Company sign is alongside the cor.
Corner is located on nearly level land, and S., 365 ft. from a graveled road, 10 ft. wide, extending N.80°E. and S.80°W.