

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 32 & 33 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 4 Page(s) 1593)

Set Fir post for sec. cor. to secs. 32 and 33, from which
A Fir 18" dia., bears N.68°E., 65 lks. dist.
A Fir 8" dia., bears N.25°W., 18 lks. dist.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #436, Surveyed May/June 1962 (DCSO records Vol. 31 Page(s) 13105)

Point for the cor. of secs. 32 and 33 only, at proportionate distance; there is no remaining evidence of the original corner point.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 22 S R 8 W

S 32 | S 33

S 5

T 23 S

1962

from which

A Fir 25" dia., bears N.5½°E., 16½ lks. dist. mkd. T22S R8W S33 BT.

A W.Fir 18" dia., bears N.20½°W., 73 lks. dist. mkd. T22S R8W S32 BT.

Corner falls at bottom of descent, slopes S.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, and crew -Dec. 27, 1966 - C.S. File 54/12-5

Found - 1962 GLO brass cap at corner, properly marked.
25" Fir now a 6 ft. high stump N.5½°E., 10.9 ft., scribe visible on pitched blaze.
18" W.Fir now 6 ft. high stump N.20½°W., 48.2 ft., scribe visible on unhealed blaze.

New BT - 7" W.Fir N.38°W., 121.5 ft. mkd. T22S R8W S32 CS BT.
No trees close to NE.

Corner lies in logged off unit 50 ft. North of new access rd.