

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1570)

Set post cor. to secs. 20, 21, 28 and 29, from which
 A Fir 24" dia., bears N.67½°W., 455 lks. dist.
 A B.Oak 30" dia., bears N.19°E., 629 lks. dist.
 A W.Oak 15" dia., bears S.43½°E., 643 lks. dist.
 No tree convenient in Sec. 29.

Fd. OK. Witness trees all standing. GLO survey by Byars, Contract #376, dated Jan. 22, 1881 (DCSO records, Vol. 4 Page 1607)

F. C. Frear - Wit: P.D. Wolford; J.H. Wolford; N.E. Richardson - June 3, 1935 - (No C.S. record source found) See "old" corner book, Page 28

Found - One old BT, a W.Oak 30" in dia., bears S.43½°E., 424.4 ft. dist. Marks plain. All other trees gone.
 Set a Cedar stake in Sawyer's garden, from which
 36" Red Fir bears N.42°W., 150 ft. dist.
 12" W.Fir bears S.48½°E., 351.5 ft. dist.

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13694)

The Sec. cor., determined at record bearing and distance from the remaining original bearing tree,
 A W.Oak 30" dia., bears S.43½°E., 643 lks. dist., with no scribe marks visible on opened and decayed blaze.
 According to a signed statement furnished by Fred F. Riley, Sr., hereto appended, there were visible scribe marks on the blaze a few years ago. This tree is accepted as the best available evidence of the original corner.

At the corner point
 Set an iron post, 28" long, 2 1/2" dia., with top 20" below surface of ground, with brass cap mkd:

T 22	S R 8 W
<u>S 20</u>	<u>S 21</u>
S 29	S 28
1963	

from which a reference monument and new bearing trees:
 An iron post, 28" long, 2½" dia., set 21" in the ground, at the corner of fences extending N. and W., for a reference monument, bears N.51¼°E., 402 lks. dist. with
 (Cont. Next Page)

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. cor. for 20, 21, 28 and 29

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

<p>brass cap mkd. T22S R8W S21 RM 1963 and an arrow pointing to the magnetic. A Fir 9" dia., bears S.49 3/4°E., 536 lks. dist. md. T22S R8W S28 BT. A Maple 36" dia., bears N.42¼°W., 332 lks. dist. mkd. T22S R8W S20 BT. Corner falls in a cultivated field. Deposit 40 lbs. of assorted scrap iron at base of corner monument.</p>
<p>Fd. and used in BLM resurvey by Brooks and Peterson, Group #'s 595 and 657, surveyed Aug. 1965/Dec. 1967 (DCSO records, Vol 34 Page 14115)</p>
<p>Fd. OK, Jan. 1994, M 120-49 A & B.</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 9/21/2005 - C.S. File 67/13-10 ----- Found - Did not dig monument up, used very strong magnetic sound for location. 36" maple now 51" dia., tagged, no blazes visible bears N.42¼°W., 250.9 ft. (rec. N.42¼°W., 219.1 ft.) 1963 BT (Possible ½ chain error, rec. 352 lks, 382 lks.?) All other accessories fd. as noted in BLM's 1963 renewal. Note - Corner lies in nearly level pasture land with no fences near.</p>
<p> </p>