

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 300621

PRIMARY CORNER DESCRIPTION Wit. M.C. of Secs. 4 and 5

Alias 877900 Description M.C. Right bank Umpqua River  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13698-99)

(22.93 chs.)

Point for witness meander corner of secs. 4 and 5, on shoulder of highway.

Set an iron post, 28" long, 2½" dia., 24" in the ground, and in a mound of stone, 2½ ft. base, to top, with brass cap marked:

T 22 S R 8 W  
W C  
^  
|  
S 5 S 4  
M C  
1963

from which

A Fir 12" dia., bears N.20¼°E., 216 lks. dist. mkd. X BT.

An Oak 15" dia., bears N.62°W., 225 lks. dist. mkd. X BT.

Deposit broken glass and set an iron pipe, 3 ft. long, ¾" dia., alongside the iron post.

(This is the only practicable location for a monument on line in the vicinity of the corner.)

(N.5°41'E., 24.225 chs.)

True point for the meander corner of secs. 4 and 5, established by Byars in 1881 (Vol. 4 Page 1604) at proportionate distance; there is no remaining evidence of the original corner. This point falls in a yard where it is impracticable to establish a permanent monument.

Douglas Co Surveyors Office - Larry E. Monrean, Deputy - P.L. Earle; K Cheney, crew - Nov. 10, 1976 - C.S. File 59/26-13

Found - A 12" now 20" Fir, bears N.20¼°E., 142.6 ft. Tree has double blaze. I open lower blaze and find scribing "T".

A 22" Maple, bears N.61½°W., 153.0 ft. (1963 BLM resurvey record is 15" Oak N.62°W., 148 ft.) Tree has double blaze, lower blaze chopped out, "BT" visible.

I find no trace of recorded objects at witness corner. This corner lies directly over large culvert under Highway #38.

At Witness corner to Meander Corner, I place a 1" x 30" I.P. with brass cap attached stamped:

(Cont. Next Page)

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 300621

PRIMARY CORNER DESCRIPTION Wit. cor. to M.C. Secs. 4 and 5

Alias <u>877900</u>	Description <u>M.C. Right bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

"Douglas County Surveyor"  
T 22 S R 8 W  
W C  
S 5 | S 4  
M C  
1976

Brass cap is set 1" above ground.  
The southerly edge of State Hwy #38 is 14.7 ft. from this corner. (Rec. 14.5 ft.) Set post and witness sign approx. 1 ft. North of cap.

---

FD. OK - Les Roberts - M 124-44 & CS 65/12-5 A&B - 2-10-97

---

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor and Michael O. Jones Surveying Technician, under Group #2199, surveyed April 2008/April 2009 - (DCSO rec. Vol. 56 Pg 21943)  
-----  
The WC to the meander cor. of secs. 4 and 5 for the right bank of the Umpqua River, established by Brooks and Jelley in 1963-65, and perpetuated by Monrean in 1976; monumented with an iron post, 1½" dia., firmly set, with top 12" below the surface of the ground, with a brass cap (properly) mkd. from which a bearing tree mkd by Brooks and Jelley in 1963-65  
A fir, 32" dia., bears N.19°E., 142.6 ft., with a healed blaze. (Record, N.20¼°E.)  
and a new bearing tree  
A maple, 21" dia., bears N.82°E., 84.0 ft., mkd. WC MC S4 BT on bark.  
Set a carsonite survey monument post alongside the cor.

From this cor., the right bank of Umpqua River bears S.5°42'51"W., 8.6 ft. bank bears N.70°E. and S.73°W.

From this same cor., the witness meander cor. of the NE. bdy. of DLC No. 49 bears S.65°17'03"W. 288.76 ft., hereinafter described.  
N.5°42'51"E., bet. secs. 4 and 5 85.47 ft.  
True point for the meander corner of secs. 4 and 5, established by Byars in 1881, at proportionate dist., there is no remaining evidence of the original cor., not monumented.

---

2