

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 33 and 34 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1565)</p> <p>-----</p> <p>Set closing cor. to secs. 33 and 34, from which A W.Oak 10" dia., bears N.77°W., 497 lks. dist. A Fir 18" dia., bears N.26°E., 548 lks. dist.</p>
<p>GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 4 Page(s) 1593)</p> <p>-----</p> <p>The cor. to secs. 33 and 34 on S. bdy. of T22S R8W, bearing trees all standing, established cor. as per instructions, from which A W.Oak 10" dia., bears N.77°W., 497 lks. dist. A Fir 18" dia., bears N.26°E., 548 lks. dist.</p>
<p>BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #436, Surveyed May/June 1962 (DCSO records Vol. 31 Page(s) 13103-04)</p> <p>-----</p> <p>The cor. of secs. 33 and 34 only, on the S. bdy. of the Tp. determined at the intersection of woven wire fences extending N. & E. and a picket fence extending W. Local residents state that these fences were located when the original corner was in existence and that the fence corner now marks the true position for the sec. cor., from which the remains of an original bearing tree: A rotted Fir stump 26" dia., bears N.26°E., 558 lks. dist. with old axe marks but no scribe marks visible on the badly decayed face of blaze. (Rec. distance, 548 lks.) At the corner point Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd: T 22 S R 8 W <u>S 33 S 34</u> S 4 T 23 S 1962</p> <p>from which new bearing trees A W.Oak 18" dia., bears N.22°E., 54 lks. dist. mkd. T22S R8W S34 BT. A W.Oak 12" dia., bears N.64°E., 33 lks. dist. mkd. X BT. No suitable BT available in section 33. Reset fence corner post alongside the iron post.</p>
<p>Cor. Fd. and used in BLM resurvey by Peter Peterson, Group #640, surveyed July 1967/Apr 1968 (DCSO Rec. Vol.35 Pg 14429)</p>

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 33 and 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Rob Ward, Ward North West Inc. - Witness: Ron Rice -
6/15/2000 - C.S. File 65/30-20

CONDITION REPORT ONLY

Found - 3¼" BLM Brass cap
30" W.Oak bears N.22°E., 35.6 ft. healed face.
23" Twin W.Oak bears N.64°E., 21.8 ft., healed face.
BLM CC Secs. 3, 4 (T23S R8W) bears S.87°46'E.,
181.32 ft.

Note - All BTs have red painted bands and faces plus yellow
BT tags. Steel post set adjacent to corner.