

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 4 Page(s) 1606)

Set Maple post for the ¼ sec. cor., from which
A Fir 16" dia., bears N.85°E., 53 lks. dist.
A Fir 18" dia., bears West, 31 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Clete Putnam, crew - June 8, 1961 - C.S. File 52/80-1

Found - 18" Fir now 27", West, 20.5 ft., uprooted and down. This tree had been opened before it fell, face down, traces of scribing visible.
16" Fir now 24" dead snag, N.85°E., 35.0 ft., shows good scar. Did not chop open.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 8 W
¼ S28 | S27
1961

New BTs -18" Fir N.42°W., 32.2 ft. mkd. ¼ S28 CS BT.
15" Fir N.20°E., 44.5 ft. mkd. ¼ S27 CS BT.

This corner lies on a steep West slope about 100 ft. West of a ridge top.

Fd. and used in BLM resurvey by Brooks and Jelley, under Group #'s 514 and 350. Surveyed June 1963/March 1965 - (DCSO records, Vol 33 Pages 13688-89)