

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1564)</p> <p>-----</p> <p>Set ¼ sec. post, from which A W.Oak 10" dia., bears S.41°E., 184 lks. dist. A W.Oak 18" dia., bears S.10°W., 275 lks. dist.</p>
<p>M. B. Germond - For: Sam Brown - 1916 - Vol. 2 Page 162 and Field book #22 Pages 5-7</p> <p>-----</p> <p>Reset with Cedar stake, 5' sq. and note old BT standard.</p>
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon Tracy, crew - Dec. 1962 - C.S. File 52/14-41</p> <p>-----</p> <p>Found - Fence corner, fences South-East and N.33°W. Old Oak, down and badly rotted, S.41°E., 121.4 ft. Found old axe marks and fragments of old face, scribing completely rotted away. No trace found of orig. SW. tree.</p> <p>Set Brass cap at cor. mkd: County Surveyors Office T 22 S R 8 W ¼ S15 S14 1962</p> <p>New BTs -32" W.Oak S.31°E., 28.0 ft. mkd. ¼ S14 CS BT. 10" D.Fir N.25°W., 102.4 ft. mkd. ¼ S15 CS BT. (Germond's renewal, 1916, and an affidavit of Henry Brown is included on the notes filed in C.S. File 52/14.)</p>
<p>Mark Smalley - For: Roseburg Resources - 12/2000 - M 132-59</p> <p>-----</p> <p>Found - 1962 County brass cap flush w/ground. 43" Oak, S.31°E., 28.0 ft. healed</p> <p>New BTs- 23" Fir, N.2°W., 19.0 ft. "¼ S BT" 8" Fir, N.26°W., 46.1 ft. "¼ S BT" 19" Fir, N.70°W., 40.5 ft. "¼ S BT"</p>
<p>Daniel Baker - For: Eagle View Mgmt Co. - 1/2020 - M177-28A-C</p> <p>-----</p> <p>Found - 2½" Douglas Co. brass cap "1962" 44" Oak, S.31°E., 28.0' to side/center-1962 BT 30" Fir, N.70°W., 40.4' to side/center 2000 BT (Rec.= N.70°W., 40.5') 20" Fir, N.25°W., 46.0' to side/center 2000 BT (Rec.= N.26°W., 46.1') 33" Fir, N.2°W., 19.5' to side/center 2000 BT (rec. = N.2°W., 19.0)</p>