

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1564)

Set post cor. of secs. 10, 11, 14 and 15, from which
A Fir 10" dia., bears S.48½°W., 315 lks. dist.
A W.Oak 24" dia., bears S.10½°E., 336 lks. dist.
A Fir 14" dia., bears N.75½°W., 788 lks. dist.
No tree visible in sec. 11.

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 4 Page(s) 1598)

Reestablished cor., witness trees all standing, viz.
A Fir 10" dia., bears S.48½°W., 315 lks. dist.
A W.Oak 24" dia., bears S.10½°E., 336 lks. dist.
A Fir 14" dia., bears N.75½°W., 788 lks. dist.

M. B. Germond - For: Sam Brown - 1916 - Vol. 2 Page 162 and Field Book #22 Pages 5-7

Rock 6 x 8 x 12 and note old BT standing.

O.F. Thiel - For: Henry Brown - April 27, 1946 - Field Book 2 Page 7

NE Corner Sec. 15. Stone corner.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - M. Stone & V. Tracy, crew - Nov. 19, 1962 - C.S. File 52/14-35

Found - Rock, 6" x 8" x 12" set by Germond, 1916. Found chiseled "X" on top of rock.
No trace of either tree marked by Germond. (I think trees referred to by Godfrey were actually by Thiel and those trees were for the 1/4 Cor. for 11 and 14. - V.L. June 1995)
40" Fir S.48½°W., 208 ft., to face, bark scribing, looks like Thiel's.
Down and badly decayed Oak S.10½°E., 222 ft., no markings.

Above two trees mentioned, fit bearing and distance of 2 orig. BTs.

Alongside Rock, Set brass cap mkd: County Surveyors Office

T 22 S R 8 W
S 10 | S 11
S 15 | S 14
1962

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. cor. for 10, 11, 14 and 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

New BTs -18" D.Fir N.2°E., 24.0 ft. mkd. T22S R8W S11 CS BT
14" D.Fir N.40°W., 6.7 ft. mkd. T22S R8W S10 CS BT
15" D.Fir S.18°E., 45.6 ft. mkd. T22S R8W S14 CS BT
An old fence corner, fences E. and S., bears NE., 2 ft. from corner.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 595 and 657 - surveyed Aug. 1965/Dec. 1967 - (DCSO records Vol. 34 Page(s) 14111-12)

The sec. cor., perpetuated and recorded by Godfrey in 1962, monumented with an iron post, 1½" dia., firmly set, projecting 8" above ground, with 1962 brass cap from which the original bearing trees

A down and decayed W. Oak size indeterminate, bears S.10½°E., 336 lks. dist. with no marks remaining.

A Fir 40" dia., bears S.48½°W., 315 lks. dist. with healed blaze and scribe marks T22S R8W visible on bark blaze. and trees mkd. by Godfrey

A Fir 20" dia., bears N.2°E., 36 lks. dist. with healed double blaze.

A Fir 18" dia., bears S.18°E., 69 lks. dist. with healed double blaze.

A Fir 16" dia., bears N.40°W., 16 lks. dist. with healed double blaze.

and a new bearing tree

A Fir 13" dia., bears S.72°W., 117 lks. dist. mkd. T22S R8W S15 BT.

Daniel Baker - For: Eagle View Management Co. Inc. - 1/2020 - M177-28A-C

Found - 2½" Douglas County brass cap "1962"
20" Fir snag, N.2°E., 24.0' to side/center 1962 BT
36" Fir, S.18°E., 45.6' to side/center - 1962 BT
20" Fir snag, S.72°W., 78.2' to side/center - 1965 BLM BT (BLM rec = 117 lks.)

33" Fir, N.38°W., 6.7' to side/center - 1962 BT (Co. rec.= N.40°W. 6.7' & BLM rec.=N.40°W 16 lks)

New - 29" Fir, N.77°E., 15.3' scribed "T22SR8WS11 BT"

13" G.Fir, S.83°W., 32.7' scribed "T22SR8WS15 BT"