

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 4 Page(s) 1598)

Set Fir post for the ¼ sec cor. bet Secs. 11 & 14, from which
A Fir 8" dia., bears North, 4 lks.
A Laurel 12" dia., bears S.10°W., 44 lks.

M. B. Germond - For: Sam Brown - 1916 - Vol. 2 Page 162 and Field Book #22 Pages 5-7

Set in:
R.Fir 20", N.66°30'E., 19½ lks.
W.Fir 16" S.9°30'W., 77 lks.

Douglas County Surveyors Office - Milo E. Godfrey, Deputy - C.S. File 52/14-134 - Nov. 14, 1962

Corner searched for, not found.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 595 and 657 - surveyed Aug. 1965/Dec. 1967 - (DCSO records Vol. 34 Page(s) 14110-11)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

¼ $\frac{S\ 11}{S\ 14}$
T 22 S R 8 W
1967

from which

A Fir 5" dia., bears N.82°W., 18 lks. dist.

A Fir 5" dia., bears S.39°E., 7 lks. dist.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor and Michael O. Jones Surveying Technician, under Group #2199, surveyed April 2008/April 2009 - (DCSO rec. Vol. 56 Pg 21954)

The ¼ sec. cor. of secs. 11 and 14, reestablished by Brooks and Peterson in 1965-67; monumented with an iron post, 2½" dia., firmly set, projecting 8" above ground, with a brass cap (properly) mkd.

from which bearing trees mkd. by Brooks and Peterson in 1965-67

A fir, 7" dia., bears S.39°E., 4.6 ft. with a healed blaze

A fir, 8" dia. bears N.82°W., 11.9 ft. with a healed blaze

continued next page

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Daniel Baker - For: Eagle View Management Co. Inc. - 1/2020 -
M177-28A-C

Found - 3¼" BLM brass cap "1967"
7" Fir snag, S.39°E., 4.6' to side/center-1967 BLM BT
8" Fir snag, N.82°W., 11.9' to side/center-1967 BLM BT
New - 10" Fir N.84°E, 6.7' to side/center-scribed "¼S11 BT"
15" Chinquapin, S.11°E., 21.6' to side/center
scribed "¼S14 BT"
12" Fir, S.32°W., 5.6' to side/center-scribed "¼S14
BT"
17" Fir, N.75°W., 19.5' to side/center-scribed "¼S11
BT"