

PRIMARY CORNER DESCRIPTION Sec. cor. for 23, 24, 25 and 26

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1556)

 Set post cor. of secs. 23, 24, 25 and 26, from which
 An Alder 18" dia., bears N.57°E., 56 lks. dist.
 A Fir 10" dia., bears S.24°E., 105 lks. dist.
 A Fir 10" dia., bears S.57°W., 43 lks. dist.
 No tree convenient in sec. 23.

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13683)

 Point for the cor. of secs. 23, 24, 25 and 26, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 22 S R 8 W	
S 23	S 24
S 26	S 25
1964	

from which

- A Fir 17" dia., bears N.25¼°E., 32 lks. dist. mkd. T22S R8W S24 BT.
- A Fir 8" dia., bears S.9½°E., 177 lks. dist. mkd. T22S R8W S25 BT.
- A Hemlock 40" dia., bears S.19½°W., 153 lks. dist. mkd. T22S R8W S26 BT.
- A Fir 32" dia., bears N.56½°W., 18 lks. dist. mkd. T22S R8W S23 BT.

Douglas Co. Surveyors Office - Milo Godfrey, Deputy - 1963 - C.S. File 52/14-68 - "Fd 1964 GLO brass cap and 4 new trees."

Fd. OK, Feb. 1992, K. Hoffine, M 114-47

Ken Hoffine - For: Lone Rock Timber Co. - 4/17/2006 - C.S. File 65/58-16

 Found - 1964 BLM brass cap on 28" iron pipe pulled out of ground & laying on edge of dirt skid road. We reset corner from remaining BTs & traverse to N 1/16 & North 1/4 as checks.

- 45" D.Fir stump N.56½°W., 12.0 as per record.
- 48" W.Fir stump S.19¼°W., 100.8 ft. (Rec. S.20°W., 101.0 ft.)
- 17" D.Fir S.12¾°E., 116.2 ft. (rec S.13°E. 116.5 ft)

continued next page

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. cor. for 23, 24, 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set - 5/8"x40" IR with yellow plastic cap mkd: LONE ROCK
TIMBER PLS 2291 0.56 ft. above ground bears
N.29¼°E., 84.5 ft.

Note - Corner lies on South edge of dirt skid road at
ground level. Put metal fence post 0.3 ft. West
of corner. Line running East & South were blazed
& painted.

Daniel Baker - For: Eagle View Management Co. Inc. - 1/2020 -
M177-28A-C

Found - 3¼" BLM brass cap "1964"
17" Fir stump, S.13°E., 116.5' to side/center-1964
BLM BT (REC = S.9½°E., 177 lks)
37" W.Fir stump, S.18°W., 100.8' to side/center-1964
BLM BT (Hemlock REC = S.19½°W., 153 lks)
34" Fir stump, N.56½°W., 12.0' to side/center-1964
BLM BT (REC = N.56½°W., 18 lks)