

PRIMARY CORNER DESCRIPTION Sec. cor. for 11, 12, 13 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1558)

Set post cor. to secs. 11, 12, 13 and 14, from which
A Fir 50" dia., bears N.70°W., 24 lks. dist.
A Fir 10" dia., bears N.57½°E., 46 lks. dist.
A Maple 15" dia., bears S.56°E., 92 lks. dist.
A Fir 48" dia., bears S.30°W., 90 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol 4 Pg 1596)

Secs. 11, 12, 13 and 14, witness trees are all standing, viz.
A Fir 50" dia., bears N.70°W., 24 lks. dist.
A Fir 10" dia., bears N.57½°E., 46 lks. dist.
A Maple 15" dia., bears S.56°E., 92 lks. dist.
A Fir 48" dia., bears S.30½°W., 90 lks. dist.
Set New Post.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon Tracy, crew - Sept/Oct. 1962 - C.S. File 52/14-34

Found - Partly rotted old Fir snag N.70°W., 15.8 ft. (to face). Cut open and found good scribing "S11 T22S R8W BT"
Burned remains of old Fir stump S.30½°W., 59.4 ft. Too far gone to find scars or scribing.
No trace of NE or SE BTs found.
Small gully running NW, 55 lks. East of corner checks call in govt. notes.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 8 W
S 11 | S 12
S 14 | S 13
1962

New BTs -7" D.Fir N.52°E., 14.9 ft. mkd. T22S R8W S12 CS BT.
14" Alder S.62°E., 34.1 ft. mkd. T22S R8W S13 CS BT
10" Maple S.87°W., 45.7 ft. mkd. T22S R8W S14 CS BT
6" Maple N.79½°W., 31.2 ft. mkd. S11 CS BT.

Corner lies on very steep NW slope, approx. 150 ft. SE of Little Paradise Creek.

Corner tied in BLM survey by Brooks and Jelley, under Group #;s 514 and 350 - surveyed June 1963/March 1965 -(DCSO records, Vol. 33 Pages 13683-84) AND used in Brooks and Peterson survey, Aug. 1965/Dec. 1967 (DCSO records. Vol. 34 Page 14109)

PRIMARY CORNER DESCRIPTION Sec. cor. for 11, 12, 13 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Fd. OK, April 1975 by Woolley Logging, C.S. File 57/21-6
Fd. OK, July 1985 by L. Roberts, M 90-74 and C.S. 63/18-4(E)

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor & Michael Jones Surveying Technician under Group #2199 surveyed April 2008/April 2009 - (DCSO rec Vol 56 Pgs 21938-9)

The cor. of secs. 11, 12, 13 & 14, perpetuated by Godfrey, in 1962-63; monumented with an iron pipe, 1½" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd. from which the remains of an original bearing tree

A fir snag, 55" dia., bears N.70°W., 15.8 ft., with illegible scribe marks visible on partially healed blaze.

and bearing trees mkd. by Godfrey in 1962-63 and reported by Brooks and Jelley in 1963-65

A fir, 28" dia., bears N.52°E., 15.2 ft., no marks visible.

A maple, 14" dia., bears S.85°W., 45.7 ft., with a healed blaze. (Record S.87°W., 46.2 ft.)

A maple, 10" dia., bears N.79½°W., 31.7 ft., with a healed blaze.

and a new bearing tree

A maple, 16" dia., bears S.23°E., 32.8 ft., mkd. S14 BT.

Daniel Baker - For: Eagle View Management Co. Inc. - 1/2020 - M177-28A-C

Found - 2½" Douglas Co. brass cap "1962"
30" Fir, N.52°E., 15.3' to side/center-1962 Co. BT (Rec. 14.9)
16" Maple, S.87°W., 45.8' to side/center-1962 Co. BT (Rec. = 45.7')
55" Fir stump, N.70°W., 15.8' to side/center - orig BT
10" Maple, N.79½°W., 31.7' to side/center-1967 BLM BT