

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 4 Page(s) 1597)

Set Fir post for the ¼ sec. cor., from which
A Fir 44" dia., bears S.55°E., 28 lks. dist.
A Fir 15" dia., bears S.55°W., 30 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon Tracy, crew - Sept. 26, 1962 - C.S. File 52/14-33

Found - 45" D.Fir S.55°E., 18.5 ft. uprooted and down, bark scribing visible "¼ S BT".
24" Fir stump S.55°W., 19.8 ft., chopped open and found bottom edge of aze scar, 75-80 years old.
Tree cut too low to find scribing.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 8 W
¼ S2|S1
1962

New BTs -13" W.Fir S.29°E., 36.7 ft. mkd. ¼ S1 CS BT.
11" W.Fir S.88°E., 29.7 ft. mkd. ¼ S1 CS BT.
No trees available West of line.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor and Michael O. Jones Surveying Technician, under Group #2199, surveyed April 2008/April 2009 - (DCSO rec. Vol. 56 Pg 21940)

The ¼ sec. cor. of secs. 1 and 2, perpetuated by Godfrey in 1962-63; monumented with an iron pipe, 1½" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees

A roothole, bears S.55°E., 18.5 ft., onside of which is a down fir, 37" dia., no marks visible.

A decayed fir stump, 13" dia., bears S.55°W., 19.8 ft. with ax mark visible and part of a healed blaze.

and new bearing trees

A fir, 16" dia., bears N.32°E., 18.8 ft., mkd. ¼ S1 BT.

A fir, 19" dia., bears N.82°W., 5.5 ft., mkd. ¼ S2 BT.