

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 603100

PRIMARY CORNER DESCRIPTION Standard cor. for Secs. 1 & 2, T23-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1551)

Set standard cor. of secs. 1 and 2, from which
A W.Oak 15" dia., bears S.51°E., 94 lks. dist.
A W.Oak 8" dia., bears S.5°W., 198 lks. dist.

Corner tied in GLO survey by Whipple, under Contract #622, dated June 23, 1893 (DCSO Records, Vol. 6 Page 2614)

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13671)

Point for the stand. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner. No permanent monument established.

Survey by Les Roberts LS #1039 - For: International Paper Co. - Oct/Dec. 1982 - C.S. File 58/280 and M 90-29

No evidence found of original corner.
Set 5/8" x 24" Iron rod at proportionate distance. Buried 0.5 ft. Rod has yellow plastic cap mkd. "Roberts L.S. 1039". (Incorrect corner bears S.89°44'34"E., 1.69 ft.)
New BTs -24" Oak S.25°W., 58.4 ft. - scribed.
32" Oak S.62°E., 165.2 ft. - scribed.
I remove incorrectly set pin on 12/30/82.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Feb. 12, 1992 - C.S. File 64/23-12

Found - 5/8" Iron rod with yellow plastic cap, 5" below ground.
24" now 25" dia. W.Oak with a fully healed double blaze, bears S.25°W., 58.4 ft. (agrees w/record)
32" now 34" W.Oak with a fully healed double blaze bears S.62°E., 165.2 ft. (agrees w/record)
New Accessories:
20" W.Oak double blazed and scribed "T23S R8W S1 CS BT" bears S.20½°E., 150.1 ft.
3½" dia. BLM brass cap/iron pipe flush with ground bears West 211.2 ft (T22S R8W SE Cor S35 BLM 1964)

Fd. Ok by C. Sweeden, 5/2006 - 2007-0081 A&B

continued next page

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 603100

PRIMARY CORNER DESCRIPTION Standard cor. for Secs. 1 & 2, T23-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Daniel Baker - For: Eagles View Management Co. Inc. - 12/2018
- M175-28A-C

Found - 5/8" rebar with yellow plastic cap marked "ROBERTS
LS1039" per M90-29
29" Oak, S.25°W., 58.4' to center - M90-29 BT
39" Oak, S.62°E., 165.2' to center - M90-29 BT
23" Oak, S.20°E., 150.0' to center - Douglas Co. BT