

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 12 and 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1559)

Set ¼ sec. post, from which
A B.Oak 10" dia., bears S.4°W., 126 lks. dist.
A B.Oak 10" dia., bears N.18°E., 79 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 4 Pg 1596)

¼ sec. cor., reestablished same as per notes, viz.
A B.Oak 10" dia., bears S.4°W., 126 lks. dist.
A B.Oak 10" dia., bears N.18°E., 79 lks. dist.

Douglas Co. Surveyors Office - Floyd J. Cole, Deputy - April 16, 1913 - Vol. 2 Page 185 and July 1913, Vol. 2 Page 191; Field Book 32 Page 32

Found both trees, one dead, marks visible.
Set sandstone 8" x 10" x 14", from which
A Maple tree 12" dia. bears S.72°E., 63.1 ft.
An Oak 28" dia. bears N.40°35'E., 273.2 ft.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - M. Stone & V. Tracy, crew - Nov/Dec. 1962 - C.S. File 52/14-42

Found - Rock set by Cole in 1913. Top 4" underground. No marks on rock.
38" W.Oak N.40½°E., 273.2 ft. Cut open and found good reverse scribing "¼", center rotted away, tree hollow.
Portion of rotted Maple stump, in place, S.72°E., 63.1 ft. Too far gone to find scribing.
No trace of either original bearing trees.
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 8 W
¼ S 12
S 13
1962
New BTs -13" B.Oak S.17½°W., 43.7ft. mkd. ¼ S13 CS BT.
7" D.Fir N.9°W., 38.3 ft. mkd. ¼ S12 CS BT.
A fence corner, fences E., W., and North, bears S.60°W., 13.0ft.

Fd. OK, Sept. 1985 by L. Roberts, M 90-74 and M 99-71

continued next page

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 12 and 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Daniel Baker - For: Eagle View Management Co. Inc. - 1/2020 - M177-28A-C

Found - 2½" Douglas Co brass cap "1962"
18" Oak, S.18°W., 43.5' to side/center-1962 Douglas
Co BT (rec S.17½°W., 43.7')
24" Fir, N.9°W., 38.1' to side/center-1962 Douglas
Co. BT (rec N.9°W., 38.3')