

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 038050

PRIMARY CORNER DESCRIPTION SE Cor. Samuel Rich DLC #38

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated Sept. 1856

Set post for SE cor. "38", from which,
A Fir 24" dia., bears N.87½°W., 100 lks.
A Fir 30" dia., bears S.20°E., 25 lks.

GLO retracement of Donation Land Claims, by George S.
Pershin, under Special Instructions - Date of contract, July
25, 1896

Cannot find any definite trace of claim corner. I find a Fir
now 36" dia. with a burnt side facing N.20°W. which could
scarcely have been caused by any other than the blaze of a
bearing tree and for additional evidence of this being the
bearing tree, I find a number of blazed trees on either side
of the line within the last 6.00 chs. I therefore, at this
point, Set a Fir post 4" sq., 4 ft. long, 24" in the ground
for SE cor. claim 38, from which
A Fir 36" dia., bears S.20°E., 25 lks. dist. which I mark
Cl. 38 BT.
A Fir 24" dia., bears West, 44 lks. dist. mkd. Cl. 38 BT.

BLM resurvey by James E. Jelley, under Group # 709, surveyed
May/Sept. 1970 (DCSO records Vol. 36 Page(s) 14904)

The SE. cor. of DLC #38, determined at record distance from
the original bearing trees:
A Fir snag 33" dia., bears S.27½°E., 25 lks. dist., with
scribe marks BT visible on opened blaze. (Rec. S.20°E)
A Fir 34" dia., bears N.87½°W., 100 lks. dist. with scribe
marks C 38 visible on bark blaze, and with a healed
blaze at the bottom.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,
with brass cap mkd:
 C 38 S 17
 T 22 S R 9 W
 1970

from which a new bearing tree:
A Maple 6" dia., bears N.38½°W., 25½ lks. dist. mkd. C 38
BT.

Fd. OK, March 1978, by Ronald Stuntzner - M 69-36

Fd. OK, Feb.1983, by Daniel Baker - M 93-58
Fd. OK, March 1986, by Lawrence Olson - M 100-65