

PRIMARY CORNER DESCRIPTION SE Cor. Edward Spicer DLC #39

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated Sept. 1856</p> <p>-----</p> <p>Set Post for SE. cor. Claim 39, from which An Oak 65" dia., bears S.38°W., 75 lks. A Dogwood 3" dia., bears N.85°W., 4 lks.</p>
<p>GLO retracement of Donation Land Claims, by George S. Pershin, under Special Instructions - Date of contract, July 25, 1896</p> <p>-----</p> <p>The SE cor. of claim 39 which is stone 5 x 4", 4" above the ground. The Oak now 18" dia., bearing S.38°W., 75 lks. dist. mkd. Cl. 39 is still standing the other bearing tree is gone. In its stead a Fir 48" dia., bears N.72°E., 152 lks. dist., I marked Cl. 39 BT.</p>
<p>Survey by Richard J. Hintz, - For: Dr. R.L. Lewis - Oct. 1971 - M 42-40</p> <p>-----</p> <p>At SE cor. DLC #39, Find 1" Iron pipe.</p>
<p>Fd. Ok by D. Bentz, Aug. 1995 - 1995-0109</p>
<p>Douglas County Surveyors Office - Randall Smith & Stephen Flause - Dec. 18, 1995 - C.S. 64/66-6</p> <p>-----</p> <p>Mon. FD. - 1½" I.D. Iron pipe protruding 22" above ground. (source unknown) I.P. leans .4' SW of plumb. Note: I.P. is called a 1" I.P on surveys of rec. Accessories Fd. - A search for BT's was made none found. A 40" dia. 8' high rotted D.Fir stump was looked into no evidence found, this stump bears N.73°E., 111' from found I.P. Note: 1896 GLO mark a 48" dia. Fir that bearing was N.72°E., 100.3'. 5/8" Iron rod protruding 2" above ground, bears S.62½°W., 84.4'. Was set in M42-40 survey.</p> <p>Mon. Set - Position of Fd. I.P. is referenced and 2 3/8 dia. Brass cap on a 1 3/3" O.D. by 32" long Iron pipe is set at reference position. BC/IP protrudes 3" above ground. 1½" I.P. is measured 43" long is set along south edge of BC/IP protrudes 2" above ground.</p> <p>(Cont. Next Page)</p>

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 039060

PRIMARY CORNER DESCRIPTION SE Cor. Edward Spicer DLC #39

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note: We found no evidence in our survey files or on the ground linking Fd. I.P. to orig. SE cor of DLC 39. We perpetrate I.P. as an important point of survey denoted as the SE cor. of DLC 39 on several surveys.

New Accessories -

20" dia. D.Fir, double blazed and scribed "SE DLC 39 CS BT", bears N.6½°E., 3.2'.

10" dia. Maple, double blazed and scribed "SE DLC 39 CS BT", bears N.21°W., 10.6' to root crown.

14" dia. D.Fir, double blazed and scribed "SE DLC 39 CS BT", bears N.89°W., 11.2'.

Fd. & used on Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19869)