

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 200552

PRIMARY CORNER DESCRIPTION Pt. on E. bdy Sec 7

Alias 038011 Description Pt. on N. bdy DLC #38
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A. Boyer, Douglas Co. Surveyor, - Bert Lane; Fred Schindler;
R.J. Andrews, witnesses - Nov. 21, 1936 - Vol. 4 Page 32;
C.S. File 23/76

Cross on rock, from which
18" Fir bears N.58°W., 17.1 ft. dist., mkd. D.C.L. S.7 BT.

Fd. Cor., Oregon State Hwy Map as filed - A-4

BLM resurvey by James E. Jelley, under Group # 709, surveyed
May/Sept. 1970 (DCSO records Vol. 36 Page(s) 14906)

Intersect the N. bdy. of DLC #38, and point for the closing
sec. cor. of secs. 7 and 8.

Set an iron post, 28" long, 2½" dia., 18" in the ground, to
bedrock, mkd. X, and in a mound of stone, 2 ft. base, to top,
with brass cap mkd:

 C C
 T 22 S | R 9 W
 S 7 | S 8
 C 38
 1970

from which a bearing object and a bearing tree established by
persons unknown,

 A sandstone outcrop, 5 x 3 x 2 ft. above ground, bears
 N.44°W., 23½ lks. dist. mkd. with an X on top.

 A Fir 42" dia., bears N.53°W., 50 lks. dist., with partial
 scribe marks visible on open blaze.

and a new bearing tree,

 An Alder 10" dia., bears N.75½°E., 63½ lks. dist. mkd.
 T22S R9W S8 CC BT.

 Deposit broken brown glass at the base of the iron post.

Found OK by T. Rambo, Aug. 1999 - M133-15

Fd. BC & sandstone 2002 M159-2 by Kris DeGroot

Fd. BC in good condition by ODOT, M. Wagstaff - 5/2011-
12/2013 - ST. HWY 38-021 E

Fd as per record May 2024 N. Hibbs - 2024-0019