

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 5 (NW Cor. Sec. 8)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1678-79)

(At 361 lks. N.0°03'E. of cor. to secs. 6 & 7,)
 Set Fir post, 5 ft. long, 4" sq., 24" in ground for closing corner to secs. 5 and 8, mkd. C C T22S R9W on the E.; S5 on the N.; and S8 on the S. faces with 5 grooves on the S. and E. sides, from which,
 A Fir 7" dia., bears N.31°30'E., 23 lks. dist. mkd. T22S R9W S5 BT.
 An Alder 4" dia., bears S.66°30'E., 26 lks. dist. mkd. T22S R9W S8 BT.
 A Fir 6" dia., bears S.30°W., 30 lks. dist. mkd. CC T22S R9W S5-8 BT.
 Destroyed marks on the BT in sec. 5 as established on the line run N.0°04'W.

A. Boyer, Douglas Co. Surveyor - Wit: Peter Lane; Will Garrison; Fred Schindler - Nov. 20, 1936 - Vol. 4 Page 32; C.S. File 23/76

Set from orig. Alder BT which is now dead and about to fall, 1¼" x 36" Pipe for cor., from which,
 A 20" Fir bears S.52½°E., 48.5 ft. mkd. CS S8 BT.
 Found and cut out original BT, Fir S.30°W., 19.8 ft.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16061)

Point for the closing cor. of secs. 5 and 8, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 22 S R 9 W
S 6 $\frac{S 5}{S 8}$ CC
1974

from which
 An Alder 12" dia., bears N.32½°E., 40 lks. dist. mkd. T22S R9W S5 CC BT.
 An Alder 9" dia., bears S.67°E., 68 lks. dist. mkd. T22S R9W S8 CC BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 5 (NW Cor. Sec. 8)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Corrective Dependent resurvey by Stephen J. Malloy and John P. Farnsworth, Cadastral Surveyors, under Group #'s 1125 and 1226, surveyed Nov./Dec. 1982 - (DCSO records Vol. 47 Page(s) 17941-42)

Intersect the E. bdy. of sec. 6.
Point for the closing cor. of secs. 5 and 8, erroneously reestablished by Wofford, etal, 1973-79, bears S.4°17'W., 0.509 chs. dist. monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. and witnessed as described in the official record.

Remove the iron post, destroy the marks on the bearing trees, and at the true corner point.

RESET the iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

```

      T 22 S  R 9 W
        S 6   S 5   C C
           S 8
           1983

```

from which new bearing trees,

An Alder 8" dia., bears N.89¼°E., 11½ lks. dist. mkd. T22S R9W S5 CC BT.

An Alder 13" dia., bears S.43°E., 21½ lks. dist. mkd. T22S R9W S8 CC BT.

From this same point, the original closing cor. of secs. 5 and 8, bears S.89°49'W., 0.068 chs. dist. determined from the remains of an original bearing tree,

A Fir stump, size indeterminate, bears N.31½°E., 23 lks. dist., with scribe marks S5 visible on opened blaze.

Survey by Lawrence B. Olsen, PLS #655 - For: International Paper Co. - March 14, 1986 - M 100-65

Found - 1983 BLM brass cap.
8" Alder bears N.89°15'E., 11.5 lks.
13" Alder S.43°E., 21.5 ft.
Set a steel fence post 1 ft. South of corner.

Found OK by T. Rambo, Aug. 1999 - M133-15