

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 240400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1639)

Set Maple post 40" x 4" dia., for the 1/4 sec. corner, from which,

A Maple 10" dia., bears N.88°E., 10 lks. dist.

A Maple 10" dia., bears S.88°E., 10 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - & Vernon "Ray" Tracy, crew - June 1962 - C.S. File 49/103-5

Renewed from Maple BT, now 33", N.88°E., 6.6 ft. Did not open for scribing, new growth on tree all on W. side, dead on E. side. Tree would have been demolished. Available trees for new BTs very scarce. Location identified by running East from corner secs. 17,18,19 & 20 and from calls on Creeks East and West of 1/4 cor. which checked calls in orig. govt. field notes. Tree showed scar on South side where other fork of tree orig. stood.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 9 W

1/4 S 17
S 20

1962

New BTs -16" Hemlock N.56°W., 95.4 ft. mkd. 1/4 S17 CS BT.

8" Maple N.88°E., 4.4 ft. mkd. 1/4 S17 CS BT. (new fork of old BT)

3" D.Fir S.12°E., 18.4 ft. mkd. 1/4 BT.

No other trees available South of line.

Fd. OK, March 1978, by Ronald Stuntzner, M 69-36