

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

Original - William H. Byars, Deputy Surveyor, Under Contract No. 279 , dated March 5, 1878 - (DCSO records Vol. 4 Page(s) 1649)

-----

Set a Fir post 5" dia., 4 ft. long, 18" in ground, for corner to secs. 4, 5, 32 and 33, from which,

- A Fir 20" dia., bears N.35°E., 35 lks. dist.
- A Fir 12" dia., bears S.55°E., 75 lks. dist.
- A Fir 36" dia., bears S.30°W., 75 lks. dist.
- A Fir 40" dia., bears N.65°W., 14 lks. dist.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Dec. 1967 - C.S. File 54/60-9

-----

Found - Orig. 40" now 36" Fir, burned stump, N.65°W., 9.2 ft. Fragmentary scribe marks on old axe blaze.  
 Orig. 36" now 26" Fir, burned stump, S.30°W., 49.5 ft. possible scribe on burned blaze.  
 No trace other orig. BTs. This area apparently burned before BTs healed over.

Set Brass cap at cor. mkd: County Surveyors Office

R9W	T 22	S	S 32	S 33
	T 23	S	S 5	S 4

1967

New BTs -14" D.Fir N.53°W., 11.6 ft. mkd. T22S R9W S32 CSBT  
 12" D.Fir N.16°E., 9.2 ft. mkd. T22S R9W S33 CSBT  
 7" D.Fir S.72°E., 6.0 ft. mkd. T23S R9W S4 CS BT.  
 11" D.Fir S.16°W., 13.9 ft. mkd. T23S R9W S5 CS BT.  
 This corner lies on westerly slope on spur ridge, course S.

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23210-1)

-----

The cor. of secs. 4, 5, 32, & 33, perpetuated by the Douglas Co. Surveyor's Office, in 1967; monumented with an iron post, 1½" dia., firmly set, projecting 5" above ground, with a brass cap (properly) mkd.  
 from which the remains of an original bearing tree  
 A decayed fir snag, 23" dia., bears N.65°W., 9.2 ft., no marks visible.  
 and the remains of the BTs mkd. by the Douglas Co Surveyor's Office  
 A fir high stump, 13" dia., bears N.15½°E., 9.0 ft., with a healed double blaze.

continued next page

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. cor. for 32 & 33; 4 & 5 T23-9

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A decayed and partially uprooted fir stump, size indeterminate, bears S.72°E., 6.0 ft., with remains of a healed blaze.

A decayed fir high stump, 15" dia., bears S.14¾°W., 13.9 ft., with a healed double blaze.

A decayed fir high stump, 21" dia., bears N.53¾°W., 11.4 ft., with a healed double blaze.

and new bearing trees

A fir, 9" dia. bears N.37½°E., 7.5 ft. mkd T22S R9W S33 BT

A fir, 6" dia., bears S.10¾°E., 18.4 ft., mkd. X BT.

A fir, 10" dia., bears S.78¾°W., 9.2 ft mkd T23S R9W S5 BT

A fir, 8" dia., bears N.23¾°W., 6.7 ft mkd T22S R9W S32 BT

Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.

Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.

An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description.