

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 32 (NW Cor. Sec. 33)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #279, dated March 5, 1878, - (DCSO records Vol. 4 Page(s) 1655)

-----  
Set Fir post 4" dia., 4 ft. long, 20" in ground, for the sec. cor. to secs. 28, 29, 32 and 33, from which,  
A Fir 20" dia., bears N.85°E., 52 lks. dist.  
A Fir 30" dia., bears S.25°E., 66 lks. dist.  
A Fir 48" dia., bears S.20°W., 22 lks. dist.  
A Fir 18" dia., bears N.40°W., 35 lks. dist.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1697)

-----  
The cor. of secs. 32 and 33, which is a post, 30" above ground, 3" sq., firmly set, and marked T22S S28 on the NE.; R9W S33 on the SE.; S32 on the SW.; and S29 on the NW. faces, with 1 notch on the S. and 4 notches on the E. edge. I obliterated marks on the NE. and NW. faces and added T22S on the SW. face, from which:  
A Fir 20" dia., bears N.85°E., 52 lks. dist. mkd. T22S R9W S28 BT.  
A Fir 30" dia., bears S.25°E., 60 lks. dist. mkd. T22S R9W S33 BT.  
A Fir 48" dia., bears S.20°W., 24 lks. dist. mkd. T22S R9W S32 BT.  
A Fir 18" dia., bears N.36°W., 37 lks. dist. mkd. T22S R9W S29 BT.  
Agreeing in part with notes furnished me by the U.S. Surveyor General. I destroyed the marks on the bearing tree in sec. 29.

Douglas County Surveyors Office - James W. Byron, Surveyor - C.S. File 54/60-20 - Dec. 1967

-----  
Corner searched for, not found. Fd. unrecorded 1½" I.R. and cap mkd. 29. No trace of any BTs to SE or SW. Possible 32/33 OBTs NE & NW. NW BT does not fit for distance by 4 ft. No scribe or axe marks found.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16053-54)

-----  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 32 (NW Cor. Sec. 33)

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

The cor. of secs. 32 and 33 only, perpetuated by person(s) unknown, monumented with an iron pipe, 2" dia., firmly set, projecting 8" above ground, with brass cap mkd. S29 S32 S33, from which the remains of the original bearing trees:

A burned and decayed Fir stump 34" dia., bears N.85°E., 52 lks. dist., no marks visible.

A burned Fir stump 60" dia., bears S.35°E., 60 lks. dist. no marks visible. (Rec. S.25°E.)

A decayed Fir stump size indeterminate, bears S.20°W., 24 lks. dist., no marks visible.

A burned Fir stump 20" dia., bears N.36°W., 37 lks. dist., no marks visible.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, directly over iron pipe, with brass cap mkd:

T 22 S R 9 W  
 \_\_\_\_\_  
 S 29  
 \_\_\_\_\_  
 S 32 | S 33  
 \_\_\_\_\_  
 1975

from which new bearing trees:

A Fir 18" dia., bears S.35°E., 9 lks. dist. mkd. T22S R9W S33 BT.

A Fir 11" dia., bears S.89°W., 58 lks. dist. mkd. T22S R9W S32 BT.

BLM Corrective Dependent resurvey by Stephen J. Malloy and John P. Farnsworth, Cadastral Surveyors, under Group #'s 1125 and 1226, surveyed Nov./Dec. 1982 - (DCSO records Vol. 47 Page(s) 17925)

-----  
(Corner Report)

The cor. of secs. 32 and 33 only, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with 1975 brass cap, from which the remains of an original bearing tree:

A burned Fir stump, 20" dia., bears N.36°W., 41 lks. dist., with axe marks visible on burned remains. (Rec. 37 lks.)

and bearing trees mkd. by Wofford, etal,

A Fir 18" dia., bears S.35°E., 9 lks. dist. with healed blaze.

A Fir 18" dia., bears S.89°W., 58 lks. dist., with healed blaze.